

Technical Journal

TITLE:

Rear roof cover with the molding line

REF NO: TJ 37644.1.1	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515 Polestar		ISSUE DATE: 2025-12-01	STATUS DATE: 2025-12-11
FUNC GROUP: 8360	FUNC DESC: Roof hatch	Page 1 of 3	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Attachment

File Name	File Size
TJ 37644.pptx	0.6506 MB

DESCRIPTION:

If customer complains that there is a visible on the rear roof cover follow advice under "Service".

CSC Customer Symptom Codes

Code	Description
6D	Sun/moon/convertible roof/Glass broken/chipped/cracked/distorted

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
814							2026-2026		-	202517-999952

Technical Journal 37644.1.1

SERVICE:

Please, **Do not** replace any parts for the symptom described in this TJ. This is a molding line and **not** damage.

Warranty claim info:

No warranty claim is accepted for this TJ.

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and subconcern area "Support not needed Polestar", use function group 8360.

To view TJ attachment continue to next page. This TJ has one attachment.

