

## Technical Journal

TITLE:

**Door panel trim surface wavy on a specific angle**

<b>REF NO:</b> TJ 37643.1.1	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b> 3 US 7515 Polestar		<b>ISSUE DATE:</b> 2025-12-01	<b>STATUS DATE:</b> 2025-12-11
<b>FUNC GROUP:</b> 8450	<b>FUNC DESC:</b> Sealing and protect. moulding for door	Page 1 of 3	

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

### Attachment

File Name	File Size
TJ 37643.pptx	1.1726 MB

### DESCRIPTION:

If customer complains that there is a wavy surface on the bottom door molding in a specific area or/or angle follow advice under "Service".

### CSC Customer Symptom Codes

Code	Description
M5	Exterior trim/components/Other trim problems

### DTC Diagnostic Trouble Codes

### Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
814							2026-2026		-	202517-999952

# Technical Journal 37643.1.1

**SERVICE:**

Please, **Do not** replace any parts for the symptom described in this TJ.

This will be more visible on these part numbers

Part number in VIDA:

1) Front door: 80017171, 80013262, 80017170, 80013274

2) Rear door: 80017169, 80013288, 80017168, 80013304

**Warranty claim info:**

No warranty claim is accepted for this TJ.

**LABOR TIME:**

Labor time subject to change without notice.

**VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and subconcern area "Support not needed Polestar", use function group 8450.

**To view TJ attachment continue to next page. This TJ has one attachment.**

Part number in VIDA:

- 1) Front door: 80017171, 80013262, 80017170, 80013274
- 2) Rear door: 80017169, 80013288, 80017168, 80013304

