

Technical Journal

TITLE:

PS No Auto Seat Adjustment While Switch Profiles

REF NO: TJ 37601.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515 Polestar		ISSUE DATE: 2025-11-20	STATUS DATE: 2025-12-11
FUNC GROUP: 8526	FUNC DESC: Adjustment device, assembly parts	Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

*VST Op number change.

If the customer **switches profiles and does not experience the automatic adjustment of driver seat and side mirrors to work**, please follow the instructions under “**Service**”.

This only applies on vehicles with core specification = **manual adjustable steering column** (RR02 Steering Column Type Steering column type B manual adj.).

CSC Customer Symptom Codes

Code	Description
UO	Front seat/Automatic adjustment (memory) does not work

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
359							2024-9999		-	202402-999952

Technical Journal 37601.1.0

SERVICE:

DO NOT replace any parts due to this symptom.

This issue is known, so **no analysis is needed** and work is ongoing to release a software improvement, as soon as we have confirmed release date this Technical Journal will be updated.

***Warranty claim info:**

No warranty claim is accepted for this TJ.

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support not needed Polestar", use function group 8526.