

**L634-
A.02.25**

To: After Sales Official Network
Subject: Toolkit reinstall
Date: 15/12/2025
Pages: 3



Campaign code:
L634-A.02.25

Campaign name:
Toolkit reinstall

Model:
Temerario

Model Year:
2026

Markets:
Austria, Azerbaijan, Belgium, Brazil, Cambodia, Czech Republic, Estonia, France, Germany, Hungary, Indonesia, Italy, Japan, Kuwait, Lebanon, Luxembourg, Malaysia, Mexico, Monaco, Netherlands, New Zealand, Norway, Poland, Portugal, Romania, Singapore, South Africa, Spain, Sweden, Switzerland, Taiwan, Turkey, United Arab Emirates, United Kingdom, United States

VIN Involved:
Until Vin 530 (included)


Important information: before proceeding with the repair, connect to the Warranty Portal and, using the "VIN Info" function, check that:

- the vehicle is actually affected by the instructions contained in this bulletin.

NOTE: some vehicles may not be affected, despite the fact that their Vehicle Identification Number (VIN) falls within the range;

- only replacement parts that correspond to the specific operation, identified by a letter (such as A, B, C, etc.), are to be used for the chassis being repaired.

Example



NOTE:

Operation A will be available only when the instructions require a preliminary check to be performed to determine whether or not the vehicle actually needs updating.

Information for the service network:

As a result of continuous product monitoring, Automobili Lamborghini S.p.A. identified the absence of a toolkit in the cars.

Solution for the field:

Toolkit reinstallation

Spare Parts:

OPERATION B

Kit	Description	Q.ty
4LA098609	Toolkit	1

The KIT contains:

Part number	Description	Q.ty
400012029	Gloves	1
N0300574	Spanner	1
400012255B	Screwdriver	1
8D0941802	Assembly Tool For Blade Fuse	1
4T0803615	Tow Hitch	1
47B012243	Extractor Hook	1

Rev.01

PUBLIC

The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A pursuant to copyright law. The company reserves the right to make updates and modifications as needed. The reprinting, reproduction, distribution to unauthorized persons and/or to third parties, and the partial or complete translation of the material contained herein are prohibited without the express written consent of Automobili Lamborghini S.p.A.

Doc. no.: L/V6_M06 Rev.[07]

1/3



Management of replaced parts:

Store the components that have been removed from the vehicle in an appropriate manner, marking them with their corresponding bar codes so that they can be identified during visits by the competent Area Manager.

Labor time:


Operation A: 0.1h
 Operation B: 0.1h

Previous bulletins superseded.

None.

Warranty claim instructions:

To request reimbursement for the repair performed, access the “LIASS” system on the Lamborghini portal and, following the instructions in the system’s “Manuals” section, generate and fill out a Warranty Request. Select the required campaign and proceed with entry; carefully read the options present in the alert message that displayed by the system (see example) and select the option performed on the vehicle.



Reimbursement will be structured as follows, on the basis of the operation performed:

OPERATION A: Check Vehicle configuration

- Labour time: 0.1 h

OPERATION B: Toolkit reinstallation


- Labour time: 0.1 h

Important information:

attach all documents generated during the work carried out, evidence of the work itself, for instance work orders and diagnostic protocols with BETA-Reports.

If one or more of these is missing, it may lead to a rejected reimbursement request.

Fill out the page in the warranty booklet (identified in the image below) in the section “Service and Recall Campaigns”:



Tools/Materials required

Code	Description.	Q.ty
n\ a	n\ a	n\ a

NOTE:

All O.D.I.S. Service technical documentation can be viewed on the app “O.D.I.S. Self Service Guide” available on Lamborghini HUB portal.



Check Method

OPERATION A

If the toolkit is already located into luggage compartment, the campaign can be considered completed with Operation A.

Repair Method

OPERATION B

Reinstall the toolkit into luggage compartment



IMPORTANT:

The compressor and tyre inflator are not included in the standard configuration of the cars.

To verify the correct configuration, check the spare parts catalogue by entering the VIN. If the compressor and tyre inflator are highlighted in red, they are included and must be ordered.



IMPORTANT:

The documents which must be provided together with the operation under warranty request are:

- *Produced Repair Order*
- *Saved Diagnostic Protocol with BETA report*

Failure to follow these procedures could lead to the request being rejected.

For more information, please contact your Area Manager or open a ticket to Technical Support in Lamborghini KEY (Request – General Information – After Sales Services - After Sales Technical Support).

Regards,
Lamborghini Service