

D048- JUMP START INFORMATION LABEL MISSING

SERVICE ACTION



AFFECTED MODELS	2025-2026 Defender OCTA
VOLUME AFFECTED	932 USA 122 CAN
REPAIR	A concern has been identified on certain 2025 model year to 2026 model year Defender OCTA vehicles where the jump start information label has not been installed in the vehicles engine compartment. Retailers are required to install the missing label.
REPAIR TIME	0.1 HRS + DIDO
CAMPAIGN LAUNCH	The Service Action bulletin was published November 18 th , 2024. Please also refer to Customer Service Parts Bulletins 252611.022 - USA and JLRCS2511.04 – Canada, published November 13 th , 2025, for details of jump start labels that have been pre-shipped to your retailer.
NOTES	Retailers are required to repair all affected vehicles in their inventory before sale and delivery. Sold vehicles are to be repaired at the next service visit. All affected VIN are flagged in the warranty portal and TOPIX. BBSS reporting for affected vehicles in retailer inventory is not yet available