



SERVICE ACTION

Global Service Action
Number: D067

Subject: Transmission Control Module (TCM) Software Update	Publication No.: D067
	Model: Range Rover (LK)
	Model Year: 2024
	Model: Range Rover Sport (L1)
	Model Year: 2024
	Date of Issue: 16 December 2025

To:	Jaguar Land Rover North America, LLC and Jaguar Land Rover Canada ULC.
For the Attention of:	The approved JLR retailer / authorized repairer.
Important:	NOTE: The information in this campaign is intended for use by professional technicians. If you are not a JLR retailer / authorized repairer, do not assume that a condition described affects a specific vehicle. Contact an authorized JLR retailer / authorized repairer to determine if this campaign applies to a specific vehicle. This campaign has been issued to provide the relevant repair instructions, parts and warranty information.

FOR THE ATTENTION OF ALL:

DESCRIPTION OF ISSUE

A potential concern has been identified on certain 2024 model year Range Rover and Range Rover Sport vehicles equipped with the 4.4 NC11 P8S engine. The [Malfunction Indicator Lamp \(MIL\)](#) is illuminated on the vehicles instrument panel cluster, due to a [Transmission Control Module \(TCM\)](#) network communication fault. There are no other effects on the vehicle, or loss of functionality.

ACTION TO BE TAKEN

At the next opportunity, you are requested to repair the vehicle.

Check the JLR Warranty Portal to make sure affected vehicles are correctly identified prior to starting this campaign. The Warranty Portal will be updated to reflect only those vehicles affected.

JLR retailers / authorized repairers are reminded that they must not sell vehicles identified as affected by this campaign until such time as the repair has been successfully completed.

An owner may indicate that a repair has already been completed for this concern, in which case the full cost of the repair should be reimbursed. Refer to the warranty section of this campaign for details of the Customer Reimbursement and Related Damage Process. At the time of confirming a booking for a vehicle repair, make sure you check the Warranty Portal to confirm if there are any other outstanding campaigns, to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed in one visit.



The following applies to:
[NORTH AMERICA]

FOR THE ATTENTION OF NORTH AMERICAN TERRITORIES ONLY:



The following applies to:
[NORTH AMERICA]

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your JLR retailer / authorized repairer. Unsold vehicles must be repaired prior to handover of the vehicle for retail sale.

Yours faithfully

Steve Oldham

Global Customer Care Quality Director

SERVICE INSTRUCTION - D067

D067 Transmission Control Module (TCM) Software update

This campaign must be completed using the campaign workflow.

Outstanding campaigns are listed on the TOPIx vehicle home page.

To complete D067 return to the TOPIx vehicle home page and select '**Start Workflow**' from the **OUTSTANDING CAMPAIGNS** section. All instructions must be followed to complete the campaign.

SROs

Description	SRO	Time
TCM - update	85.44.05	0.2
Software level check	85.99.41	0.1
Drive in / drive out	02.02.02	0.2

NOTE:

Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

Warranty Information

Warranty claims must be submitted quoting program code D067 with the relevant option code from the table below. As option codes are used there is no requirement for you to enter SROs or parts, these are included for information only.

NOTES:

- If the module(s) software is already up to date; you must not continue with the campaign. Only claim the relevant option code for diagnostic software level check.
- Option codes Y and Z are ONLY to be used when the Software is already at the latest level.

Program	Option	Description	SRO	Time
D067	A	TCM - update	85.44.05	0.2
D067	B	TCM - update Drive in / drive out	85.44.05 02.02.02	0.2 0.2
D067	Y	Software level check	85.99.41	0.1
D067	Z	Software level check Drive in / drive out	85.99.41 02.02.02	0.1 0.2

NOTE:

The option that contains the drive in / drive out allowance may only be claimed when the vehicle has been brought back into the workshop for this action alone to be undertaken.

Warranty claims must be submitted in accordance with the current JLR Global Warranty Manual, and its amendments, unless stated otherwise in this campaign.

Customer Reimbursement and Related Damage Process

NOTE:

If there is a requirement to claim for related / consequential damage or customer reimbursement, refer to the related instruction that can be found in TOPIx (in the Search box, search for 'Related Damage Claim' and open the related bulletin link).

DIAGNOSTIC INSTRUCTION

CAUTIONS:

- All content in the Diagnostic Instruction **MUST** be read before selecting 'Complete Step'.
- You **MUST** connect the JLR approved diagnostic equipment and approved battery support unit. To complete the campaign workflow.

NOTE:

Option codes Y and Z are ONLY to be used when the Software is already at the latest level.

1. Connect the JLR approved diagnostic equipment and the approved battery support unit.

2.

CAUTION:

The campaign workflow **MUST** be run for the software update to be applied.

Select 'Complete Step' and follow all on-screen instructions.

3. Disconnect the JLR approved diagnostic equipment and the approved battery support unit.