



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This bulletin supersedes TSB JLRTB02052NAS5/2024 dated 20 SEP 2024, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page). Only refer to the electronic version of this Technical Bulletin in TOPIx.

Changes are highlighted in blue

SECTION:

501-03

SUBJECT /CONCERN:

RESCINDED - Rear Doors Difficult To Open - RESCINDED

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
Defender (LE)	2020-2024	000431-356580	Nitra (Slovakia)	5-Door

MARKETS:

NORTH AMERICA

**CONDITION
SUMMARY:****SITUATION:**

This bulletin has been rescinded with immediate effect. TOPIx workflow must be used to investigate the vehicle concerns.

CAUSE:

N/A

ACTION:

N/A