

Vermeer MV Solutions, Inc.

Trenchless
 Piedmont, South Carolina 29673 USA

FIELD CAMPAIGN SERVICE BULLETIN #: SMV2026-002

DATE: 2025 December 30

CAMPAIGN TYPE: Mandatory - Product Compliance
DEALER INSTALLATION ONLY

CAMPAIGN CATEGORY: Bulletin Only

MACHINE/ ATTACHMENT MODEL(S):	SERIAL NUMBERS:		Kit version
	Included	Excluded	
CS418B	[REDACTED]	None	N/A
CSGT	[REDACTED]	None	N/A
CVGT	[REDACTED]	None	N/A
CVSGT	[REDACTED]	None	N/A
EVGT	[REDACTED]	None	N/A
LPMINI	[REDACTED]	None	N/A
LPSDT	[REDACTED]	None	N/A
LPSGT	[REDACTED]	None	N/A
LPXDT	[REDACTED]	None	N/A
VX75G2	[REDACTED]	None	N/A

Subject:



Weight Rating VIN Plate
Replacement Kit
(SMV2026-002)

Background:

INCORRECT GVWR AND GAWR VALUES

Due to a clerical error, Gross Vehicle Weight Rating (GVWR) and Gross Axle Weight Rating (GAWR) values were incorrectly identified on the VIN plates affixed to affected machines.

Solution:

IMMEDIATE MACHINE MODIFICATIONS REQUIRED

SMV2026-002 has been created to provide the necessary parts and instructions to install updated VIN plates on affected machines reflecting correct GVWR and GAWR values. **This kit must be installed as soon as possible.**

DEALER PARTICIPATION

REVIEW REPORT, ORDER KITS, CONTACT CUSTOMERS

1. **Review report.** Reports which will be emailed during the week of December 30, 2025, to dealerships shown in our records which have units in their territory affected by this alert. Please review the report for accuracy, including owner and/or address changes.

If the information contained in the report is NOT correct, please notify the product safety and compliance department on or before January 12, 2026, at:

Telephone: 641-621-7060

Fax: 641-621-8562

Email: productsafety@vermeer.com

2. **Dealership orders kits** by filling out the request form located on VermeerOne by filling out the request form located on VermeerOne → Service → Service Resources and then email the form to productsafety@vermeer.com. **Do not order more kits than needed for immediate installation.**
3. **Contact your affected customer(s)** to schedule a mutually acceptable time to upgrade their machine(s). **Note:** Letters will be sent to the customer(s) on or about **January 13, 2026**. *Also refer to Owner Notification section below.*

If you have any questions concerning the installation of SMV2026-002, please contact the MV Solutions service department.

REIMBURSEMENT

Kit installation. Upon completion of each kit installation, a campaign warranty claim must be submitted to the warranty department for reimbursement of the cost of parts and labor to install the kit. Labor hours to install: 0.5 hours.

Note: *Future notices to dealers and owners are dependent upon the receipt of warranty claims.*

OWNER NOTIFICATION

Sample letter: Included at the end of this bulletin is a sample letter which will be sent by Vermeer Corporation directly to the owners on or about January 13, 2026. Owner registrations indicate no translations are required for this campaign. The owner letter will only be available in English.

This owner notification/letter instructs the owner **to contact their local dealership** to arrange for a time to have the kit installed. After receiving SMV2026-002 from the parts distribution center, you must contact your affected customer(s) immediately and schedule a mutually acceptable time to upgrade their machine.

We regret any inconvenience these corrective measures may cause you. The required work is to ensure your machine is in compliance with Title 49, Part 567, of the U.S. Code of Federal Regulations.

PRODUCT COMPLIANCE DEPARTMENT

<p>Completion schedule:</p> <p><input type="checkbox"/> Product Safety Alert: Install immediately</p> <p><input checked="" type="checkbox"/> Product Compliance Alert: Install immediately</p> <p><input type="checkbox"/> 180 days from the date of this bulletin</p> <p><input type="checkbox"/> 1 year from the date of this bulletin</p> <p><input type="checkbox"/> N/A</p>	<p>Reimbursement:</p> <p><input type="checkbox"/> Product Safety Alert</p> <p><input checked="" type="checkbox"/> Product Compliance Alert</p> <p><input checked="" type="checkbox"/> All units listed above</p> <p style="padding-left: 20px;"><input checked="" type="checkbox"/> Parts <input checked="" type="checkbox"/> Labor paid (Labor code: SB26)</p> <p><input type="checkbox"/> No reimbursement</p>
--	---

Internal reference: TREAD Act Code <i>(Choose one or more applicable codes)</i>	<input checked="" type="checkbox"/>	--	Not applicable	<input type="checkbox"/>	12	Exterior lighting
	<input type="checkbox"/>	02	Suspension	<input type="checkbox"/>	16	Structure
	<input type="checkbox"/>	03	Service brake system, hydraulic	<input type="checkbox"/>	17	Latch
	<input type="checkbox"/>	04	Service brake system, air	<input type="checkbox"/>	19	Tires
	<input type="checkbox"/>	05	Parking brake	<input type="checkbox"/>	20	Wheels
	<input type="checkbox"/>	11	Electrical	<input type="checkbox"/>	21	Trailer hitch



Product Compliance Department
 Vermeer Corporation
 1210 Vermeer Rd East
 Pella, Iowa 50219 USA
 productsafety@vermeer.com

**SAMPLE
 OWNER
 LETTER**



PRODUCT COMPLIANCE

First Notice

Weight Rating VIN Plate Replacement Kit (SMV2026-002)

Model: «Model»

Serial #: «SerialN»

January 13, 2026

Dear «MODEL» owner:

According to our records, you currently own a Vermeer «MODEL» <PRODUCT FAMILY>. The model and serial number are shown at the top center of this letter.

INCORRECT GVWR AND GAWR VALUES

Due to a clerical error, Gross Vehicle Weight Rating (GVWR) and Gross Axle Weight Rating (GAWR) values were incorrectly identified on the VIN plates affixed to affected machines.

IMMEDIATE MACHINE MODIFICATIONS REQUIRED

SMV2026-002 has been created to provide the necessary parts and instructions to install updated VIN plates on affected machines reflecting correct GVWR and GAWR values. **This kit must be installed as soon as possible.**

Please contact your authorized, independent Vermeer dealer immediately to arrange a mutually acceptable time and location to install SMV2026-002 at no cost to you for labor or materials. If the Vermeer dealer travels to the unit to install the kit, costs may be incurred by the owner. **You must have your machine upgraded to ensure product compliance.**

Contact your local Vermeer dealer: «Service_Dealer_Name»
 «Serv_Dealer_Add1» «Serv_Dealer_Add2»
 «Serv_Dealer_City» «Serv_Dealer_St» «Serv_Dealer_Zip»
 «SERV_DEALER_COUNTRY»

Telephone: «Serv_Dealer_Phone»

If you no longer own this unit, please notify the product safety and compliance department at:

Toll-free: 800-829-0051, option 1
 Telephone: 641-621-7060
 Email: productsafety@vermeer.com

If possible, please provide the name and address of the new owner.

We regret any inconvenience that these corrective measures may cause you. The required work is to ensure your machine is in compliance with Title 49, Part 567, of the U.S. Federal Code of Federal Regulations.

Regards,
PRODUCT COMPLIANCE DEPARTMENT