

2025 Ontour

2. all three drawers under the stove come open while driving - misadjusted - prep and adjust lower catch, check and test operations - req 0.40 hrs **0.3 approved.**

6. rear cabinet latch does not hold - misadjusted - prep and adjust cabinet catch, check and test operations - req 0.20 hrs **0.2 approved.**