

2024 Plateau

TOUCH SCREEN @REAR OF UNIT GLITCHES OUT AND GOES BLANK. INSPECTED UNIT TOUCH SCREENS AND FOUND THAT THE REAR SCREEN WILL RANDOMLY GLITCH OUT AND GO BLANK. IT COMPLETELY LOSE CONTROLS. TRIED TO REBOOT BY DISCONNECTING BATTERIES AND IT WILL RESET SOMETIMES. HOW EVER SOMETIMES IT TAKES SEVERAL RESETS TO GET SCREEN TO REBOOT PROPERLY.

Spyder approved the replacement touchscreens, they sent you an order link

Shipping from Spyder usually takes 10 days to get to the address you provided on the order.

It's important both touchscreens are replaced to avoid issue from happening again. The time approved is 0.6 hour to R/R both touchscreens.