

[26-01-002G - Side Curtain Airbag Correction \(Recall 029G\).\(posted on 01.08.26\).pdf](#)

Hyundai Motor America (HMA) has launched Limited Coverage Campaign LA5 for the High Mounted Stop Lamp Adhesive Residue Inspection & Stop Lamp Replacement!

****This campaign is to be performed on vehicles pending initial retail in dealer inventory and strongly encouraged to be completed prior to retail delivery to a customer.****

A. Affected Vehicles:

- Certain 2026MY IONIQ 9 (ME1A EV) produced from 02/28/2025 – 01/06/2026

- VIN Identification: Use the 'Vehicle Information' screen in WebDCS under the 'Campaign Not Performed' section to determine campaign applicability.

B. Campaign Description:

Certain IONIQ 9 (ME1A EV) vehicles may exhibit adhesive residue on the high mounted stop lamp. This can occur when the clear protective film has had prolonged exposure to sun and heat, causing some of the adhesive to remain on the black plastic housing after removal. **Technical Service Bulletin (TSB) 26-01-001H** provides instructions to inspect and, if necessary, replace the high mounted stop lamp on affected vehicles.

C. Campaign Document(s):

1. TSB 26-01-001H

A. Available on Hyundaidealer.com > Service > HMA Tech Info > Campaign

D. Parts Ordering/Information:

1. Parts may be ordered through the normal WebDCS ordering process.

A. Lamp Assembly – High Mounted Stop

2. Parts will initially be set on Campaign Parts Management (CPM) of 1 such that the dealer needs to submit its corresponding campaign claims to order additional parts.

E. Action Required:

1. Confirm VIN eligibility for campaign via WebDCS.

2. **Follow TSB 26-01-001H** for service procedure to inspect the high mounted stop lamp and if necessary, replace the lamp.

3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.

Thank you for your patience and understanding.

Warranty Campaign Team
Hyundai Motor America