



# Service Bulletin

Bulletin No.: PIT6436A

Date: January, 2026

## PRELIMINARY INFORMATION

**Subject: Malfunction Indicator Lamp (MIL) DTC U0265 That May Set As Current Or Failed In History**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer EV	2024 - 2026		All	All	All	All
Chevrolet	Colorado	2024 - 2026		All	All	All	All
Chevrolet	Equinox EV	2024 - 2026		All	All	All	All
Chevrolet	Silverado EV	2024 - 2026		All	All	All	All
GMC	Canyon	2024 - 2026		All	All	All	All
GMC	Sierra EV	2024-2026		All	All	All	All

<b>Involved Region or Country</b>	United States, Canada, Mexico and South Korea
<b>Condition</b>	Some customers may comment on a Malfunction Indicator Lamp (MIL). The Malfunction Indicator Lamp (MIL) may be intermittent and not be present at the time the vehicle comes in for service. Some technicians may find DTC U0265 That May Set As Current Or Failed In History in the K9 Body Control Module.
<b>Cause</b>	Engineering is currently investigating.

### Correction

Do not replace any parts including the K9 Body Control Module or the B174W Front View Camera - Windshield.

Please advise the customer they may continue to drive the vehicle. The current concern may be a potential customer dissatisfier, but it is not a Safety Issue and does not create a substantial loss of use or value.

The PI will be updated or replaced with a TSB once a determination has been made.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2880578*	Verify DTC U0265 customers concern	0.3 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version	2
Modified	09/19/2025 - Created on. 01/12/2026 - Updated vehicle list.

