



Service Bulletin

Bulletin No.: PIP6097

Date: January, 2026

PRELIMINARY INFORMATION

Subject: SES MIL DTC P0421

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 6500	2023		All	All	6.6 L5D	All

Involved Region or Country	North America
Condition	Intermittent SES MIL with DTC P0421 - Catalyst 1 Low Efficiency
Cause	Engineering currently investigating

Correction

1. Perform standard SI diagnostics for all stored or active DTCs.
2. If diagnostics identify a failed component, complete repairs as required.
3. If P0421 diagnostics are inconclusive or previous repairs have already been attempted, do NOT replace any additional Exhaust Aftertreatment Components.
4. Engineering is currently investigating and this PI will be updated or replaced with TSB once a determination has been made.
5. In the meantime, please advise customer they may continue to drive the vehicle.

Version	1
Modified	01/16/26 Created on

