



Service Bulletin

Bulletin No.: PIP6098

Date: January, 2026

PRELIMINARY INFORMATION

Subject: Diagnostic Tip : Hard Start - Rough Idle - Heavy Smoke From the Tail Pipe - Strong Diesel Smell - Hesitation Stall or No Start

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
All	All	All		All	All	All	All

Involved Region or Country	North America
Condition	Hard Start, Rough Idle, Heavy smoke from the tail pipe, strong diesel smell, Hesitation, DTCs: P0087, P0100, P0101, P0102, P0103, P0104, P0113, P0130, P0167, P0171, P0172, P0174, P0175, P0178, P0179, P0190, P0191, P0192, P0193, P0300, P0301, P0302, P0303, P0304, P0305, P0306, P0307, P0308, P0324, P0420, P0230, P2195, P2196, P2197, P2198 Misfire Codes - Diesel contamination prevents proper combustion, so misfires are likely to occur.
Cause	Possible Fuel Contamination

Correction

Repairs caused by contaminated fuel are not covered under the warranty because the issue is related to fuel quality outside manufacturer control.

Impacted vehicles are not eligible for goodwill assistance as it relates to contaminated fuel repairs.

Consumers may need to seek reimbursement from the fuel station, distributor, or their insurance provider.

Per the advice of the Colorado Division of Oil and Public Safety, keep all receipts for any expenses related to the contaminated fuel.

Version	1
Modified	1/14/2026 - Created

