



Service Bulletin

Bulletin No.: PIP6099

Date: January, 2026

PRELIMINARY INFORMATION

Subject: DTC P16F4 Service Transmission Message on DIC

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2026		ALL	ALL	ALL	ALL
Buick	Envision	2026		ALL	ALL	ALL	ALL
Cadillac	Escalade	2026		ALL	ALL	ALL	ALL
Cadillac	ESCALADE IQ	2026		ALL	ALL	ALL	ALL
Cadillac	LYRIQ	2026		ALL	ALL	ALL	ALL
Cadillac	OPTIQ	2026		ALL	ALL	ALL	ALL
Cadillac	VISTIQ	2026		ALL	ALL	ALL	ALL
Chevrolet	Blazer EV	2026		ALL	ALL	ALL	ALL
Chevrolet	Brightdrop	2026		ALL	ALL	ALL	ALL
Chevrolet	Equinox	2026		ALL	ALL	ALL	ALL
Chevrolet	Equinox EV	2026		ALL	ALL	ALL	ALL
Chevrolet	Silverado EV	2026		ALL	ALL	ALL	ALL
Chevrolet	Suburban	2026		ALL	ALL	ALL	ALL
Chevrolet	Tahoe	2026		ALL	ALL	ALL	ALL
Chevrolet	Traverse	2026		ALL	ALL	ALL	ALL
GMC	Acadia	2026		ALL	ALL	ALL	ALL
GMC	Sierra EV	2026		ALL	ALL	ALL	ALL
GMC	Terrain	2026		ALL	ALL	ALL	ALL
GMC	Yukon	2026		ALL	ALL	ALL	ALL
GMC	Yukon XL	2026		ALL	ALL	ALL	ALL

Involved Region or Country	North America
Condition	Some customers may experience a condition where the Check Engine Light has illuminated and, in some cases, a Service Transmission Message is displayed on the DIC.
Cause	Engine Control Module (ECM) Internal Software for BEV applications Battery Energy Control Module (BECM).

Note: The Transmission Control Module (TCM) is not the cause of the P16F4 and it should not be replaced.

Correction

Confirm DTC P16F4 has set and Contact Technical Assistance Center (TAC) to establish a TAC case so that an FSE can be dispatched to collect a Data Pull.

Version	1
Modified	01/16/2026 Created.

