

MAS004988 RU 25-34

RAPID UPDATE

FROM: Maserati TSO

TO: Maserati Network



Maserati

PERSONAL SERVICE LAB

MASTERS OF CARE

Rapid Update 807 GranTurismo Folgore – A-pillar replacement



DATE: January 02, 2026

Certain Maserati vehicles listed in MODISCS+ are involved in a Rapid Update to replace the the left windshield A-pillar trim.

VEHICLES INVOLVED: (M189) GranTurismo MY25

A batch of components intended for assembly may contain contamination, which could affect the positioning of the trim fabric and lead to visible wrinkles. This condition is cosmetic only and does not impact the vehicle's safety or functionality.

Fix: Replace the left windshield A-pillar trim.

We remind you that all the Rapid Updates must be performed within the first workshop visit, regardless of the Mandatory setting set in Modis, as required by Maserati policies.

Also, for vehicles in Stock Dealer / PDI, it is necessary to carry out all action operations before delivery to the end customer, as required by the White Book and explicitly reported in the Pre-delivery checklist.

Please read and review this bulletin first before ordering parts and/or starting the procedure.

Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions.

Thank You for your continued support and cooperation.


Maserati Americas
Aftersales Dept.

Technical Procedure



All images shown in this bulletin are for illustrative purposes only

1. Always check ModisCS+ to see if the vehicle is involved in this action and if it has not been previously performed.
2. Make sure you use all the precautions to work inside the vehicle and avoid any type of dirt from ruining the interior of the vehicle.
3. Replace the covers following the procedure in the workshop manual:
 - a. **9.44.002 LH WINDSCREEN PILLAR COVER. Removal-Refitting or Replacement**



4. Reassemble all removed parts following the procedure in reverse order.
5. Procedure complete.

Parts Information

To perform this action, please order the following PN

Description	Part number	Amount
LEFT FRONT PILLAR COVER – Econyl BLACK	670316508	1

Warranty Claim Information

Please complete the warranty request as follows:

Description	Code
Number of Rapid Updates	807
Warranty code	23
Error code	063
Component Code	9.44.001
Operation Code	
<ul style="list-style-type: none"> ▪ Component Replacement (1 Sides) 	9.44.001.D (0.05 h)