

MAS004999 RU 26-01

RAPID UPDATE

FROM: Maserati TSO

TO: Maserati Network



Maserati

PERSONAL SERVICE LAB

MASTERS OF CARE

Rapid Update 810 MC20 Ceiling Light Clip Position Check

TECHNICAL SERVICE OPERATIONS



DATE: January 13, 2026

Certain Maserati vehicles listed in MODISCS+ are involved in a Rapid Update to check and, if necessary, restore the correct position of the plastic clip inside the interior ceiling light.

VEHICLES INVOLVED: (M240) MC20, (M241) MC20 Cielo and GT2 Stradale (All MY25)

Some MC20 vehicles may have a ceiling light clip near the windshield that is not fully seated. If the clip moves, it can cause minor noise or vibration. This does not affect safety or function but may be annoying. This update ensures the clip is correctly positioned for best performance.

We remind you that all the Rapid Updates must be performed within the first workshop visit, regardless of the Mandatory setting set in Modis, as required by Maserati policies.

Also, for vehicles in Stock Dealer / PDI, it is necessary to carry out all action operations before delivery to the end customer, as required by the White Book and explicitly reported in the Pre-delivery checklist.

Please read and review this bulletin first before ordering parts and/or starting the procedure.

Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions.

Thank You for your continued support and cooperation.

Maserati Americas
Aftersales Dept.

OVERVIEW


What to Do

1. **Check the Clip**
 - Remove the front trim of the interior rearview mirror (see Workshop Manual procedure 9.35.032).
 - Locate the clip inside the ceiling light near the windshield.
 - Make sure the clip is secure and does not move.
2. **Fix if Needed**
 - If the clip is loose or out of place, press it back until you hear a clear "click."
 - Confirm the clip is locked in position before closing the cover.
 - Reinstall all removed parts in reverse order.

Technical Procedure

 All images shown in this bulletin are for illustrative purposes only

1. Always check ModisCS+ to see if the vehicle is involved in this action and if it has not been previously performed.
2. Make sure to always apply interior protection whenever performing repairs inside the vehicle.
3. To check that the clip is correctly secured in its seat, remove the front trim of the interior rearview mirror, following the procedure given in the workshop manual:
 - a. **9.35.032 - FRONT REARVIEW MIRROR COVER - Removal/refitting or replacement**




2. Locate the clip and check that it does not move from its seat.



3. If the clip is loose or out of its housing, reposition it and press firmly until you hear a distinct "click." This sound confirms the clip is **fully engaged** and locked into place.

4. **Check** that the clip is correctly secured before closing the cover.



5. Reinstall all removed parts by following the disassembly steps in reverse order.
6. Procedure complete.

Warranty Claim Information

Description	Code
Rapid Update Number	810
Warranty code	23
Error code	063
Component Code	9.35.032
Operation Code	
▪ Check	9.35.032.A (0.05 h)
▪ Clip Recovery	9.35.032.B (0.05 h)