

Preview Solution CBR-2399-9

Daycab Cab Roof Antenna Misalignment Causing Water Intrusion

Published 20 January 2026

Valid For

Volvo Chassis - VN (4)
Mack Chassis - AN (4), PR (4)
Model year 2025

Issue:

A mismatch between the cab roof hole geometry and the antenna in Daycab models has been identified, leading to potential water leaks into the cab.



Bad sealing because of the wrong fitting of the antenna in the roof

Correct sealing.

- **Action:**

- Use installation steps to ensure proper alignment of the antenna with the cab roof hole.
- Ensure the antenna "clicks" securely into place.
- Confirm that all four corners of the antenna are properly aligned with the cab roof opening to eliminate air gaps.

NOTE: A list of replacement instructions can be found in Impact document 3970-03-02-11 (Communication System Antenna, Replacement).



Correct sealing.

This containment solution addresses the immediate issue while a long-term fix is being developed.

Related links and attachments

[KC-2399 3970-03-02-11](#)



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article