

| | | | |
|--|--|---|---|
| Bulletin #: C32-0126-0603 | | <input type="checkbox"/> Take Note | <input checked="" type="checkbox"/> Take Action |
| <input type="checkbox"/> Retail Operator | <input type="checkbox"/> Sales Pre-Owned | <input type="checkbox"/> Business Manager | <input checked="" type="checkbox"/> Parts & Accessories |
| <input type="checkbox"/> General Manager | <input type="checkbox"/> Sales New Car | <input type="checkbox"/> Service | <input type="checkbox"/> Administration |
| Name: | | Phone Number: | |
| Title: | | Source: Parts Logistics | |
| Date: January 16, 2026 | | Supersedes: | |



BMW PARTS BULLETIN

TEC821 DOOR RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following affected part numbers:

41 51 5 A6A 223

41 51 5 A6A 224

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far missing underlining adhesive on side impact strut. Please see image below for impact strut location.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC821 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC821 is valid from January 16, 2026, through January 30, 2026. The deadline for filing a claim under TEC821 is January 30, 2026. All parts must be returned to your facing RDC no later than February 13, 2026.

Please reorder the same part number as needed.

