

43-085: Greenhouse Gas (GHG) Label Replacement

1/7/2026

 [Edit](#)  [Clone](#)

43-085

Section

Inlet/Exhaust/Aftertreatment - 43

Subject

Greenhouse Gas (GHG) Label Replacement

Whats New Abstract

Certain vehicle model year 2026 T880 / W900 / W990 chassis have updated GHG labels available for order and installation.

Condition

Certain chassis were re-classified from heavy duty tractors to vocational tractors to earn additional GHG credits. An updated GHG label is available for order and installation. This update will ensure the chassis is equipped with the most accurate information.

Chassis Affected

42 Canadian vehicle model year 2026 T880 / W900 / W990 built from 01/06/2025 through 05/23/2025 equipped with an outdated GHG label.

Action

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

Campaign

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
2. Ensure all required parts have arrived before scheduling the chassis for repair.
3. In Service Management, select campaign **43-085** to add it to the case. If the unit is released back into service without performing the repair, make sure to also release the campaign in Service Management.
4. If you are not using Service Management to start repair orders, review SIR for Complete next to the **43-085** campaign code prior to performing this repair.
5. Follow the procedures in the Attachments section to replace the GHG label.

Warranty

Starting on **01/07/2025** and for repairs completed by **03/16/2026** Kenworth will pay for parts at dealer net

plus applicable mark-up and labor:

- **0.3 hours** of labor to replace the current GHG label with an updated GHG label, take and email photos. Select Recommended Repair code **43-085**.
- Take photos of both the removed and newly installed GHG labels. For payment and compliance reporting:
 - Attach the photos to the warranty claim.
 - Email the photos to KW.Marketing.GHG@PACCAR.com with "43-085 and VIN" in the subject line (e.g., 43-085 1XKZDP9X6SR178940).
 - The pictures should clearly show the VIN and Family Name (see photo for examples in Procedures).
- File an additional claim for extraordinary circumstances. A Recommended Repair for standard labor must be filed first.
- File the claim within 14 days in accordance with the Warranty Policy.

Take-Off Parts Disposition:

Destroy 30 days after claim is paid

PRWS CLAIM CODING			
Campaign Code:	43-085	Campaign Type	Field Repair
Claim Category:	Truck	Repair Type	Proactive
Customer Concern Code	173	Causal Code	A1
Corrective Action Code	12	Responsibility Code:	CAMP-Campaign
Failure Location	053-005-021	Causal Part	S53-6198
Supplier Code	N/A	SRT Code	B25-44A 0.3 hours Bulletin 43-085 - Greenhouse Gas label replacement per bulletin procedure

Parts

Parts are available from PACCAR Parts. To order the correct label, follow the TCS365 Case Creation Guide for GHG labels below:

Quantity	Part Number	Description	Stock Location
1	S53-6198	LABEL- GREEN HOUSE GAS	PACCAR PARTS PDC

TCS365 Case Creation Guide for GHG Labels

Submission of a TCS365 case to **SPECIAL ORDERS** is required to order the correct chassis specific GHG label.

1. Open TCS365 in Google Chrome or Microsoft Edge.
2. Select **Order Support | Order Inquiry**
3. Select Case Type: **Place an Order**
4. Select Case Category: **Labels**
5. On the Label Order page, fill in the following fields as shown and fill in the other fields as appropriate:
 - o Account Name: Appropriate for your dealer
 - o Vehicle Year: Chassis model year
 - o Subject: **43-085 GHG Label Replacement**
 - o Dealer PO#: Dealer purchase order number
 - o Shipping method: Select from drop-down list
 - o Part Number: **S53-6198**
 - o Vehicle OEM: Select from drop-down list
 - o Vehicle Chassis Number: **Last 8 digits of VIN**

Procedure

Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained.

Please see the Attachments section below for procedures to replace the GHG label.

Attachments

[43-085 Chassis List](#)

[43-085 Repair Procedure](#)

[43-085 CAN Customer Letter](#)



A **PACCAR** COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

[Date]

Subject: 43-085: Greenhouse Gas (GHG) Label Replacement

Expiration Date: 03/16/2026



FIELD SERVICE CAMPAIGN

This notice applies to your vehicle(s) with VIN(s) at the bottom or back of this page.

Dear Kenworth Customer,

Kenworth Truck Company has determined that certain T880, W900 and W990 vehicles built during 01/06/2025 through 05/23/2025 are eligible for updated GHG labels that comply with emissions regulatory standards.

What is the problem?	Your vehicle is eligible for an updated GHG label.
What will your dealer do?	Install an updated GHG label free of charge.
What should you do?	Contact your dealer to schedule a repair appointment. This service may require up to 1 hour of labor.

To locate your nearest dealer please scan the QR code at the top of this letter or use the Dealer Locator at www.Kenworth.com. When scheduling this service, please refer to campaign 43-085: Greenhouse Gas Label Replacement and the VIN(s) listed in this letter.

If you no longer own the vehicle(s), please send an email to servicebulletins@paccar.com with the complete VIN(s) and the name and address of the new owner.

We appreciate your attention to this matter and value your loyalty to Kenworth and its dealer network.

Sincerely,

Kenworth Customer Service