

**In-Vehicle / In-App Communication
Service Action Notification-Reminder
22 Jan 2026**

| Title | Text | Short Text | Pop-Up |
|--|--|--|--|
| Service Action: Right Rear Output Shaft | <p>The right rear drive shaft may not have been manufactured correctly during production and may break. In the event of a fault, you will hear significant noises in the area of the rear axle and the driving performance will be noticeably reduced. At the same time, warning lights and Check Control messages will be shown on the Central Display.</p> <p>Contact an authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.</p> | <p>Service Action: Right Rear Output Shaft. Contact an authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer</p> | <p>Service Action: Right Rear Output Shaft. Contact an authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer</p> |