

**In-Vehicle / In-App Communication
Service Action Notification-Reminder
22 Jan 2026**

Title	Text	Short Text	Pop-Up
Service Action: Starter Motor	<p>High impact energy may cause the circlip for the starter motor pinion positioning to break which may cause the pinion to move in the direction of the starter jaw, causing damage of the starter motor. Also, consequential damage to the flywheel (torsional vibration damper) and transmission may occur.</p> <p>Contact an authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.</p>	<p>Service Action: Starter Motor. Contact an authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer</p>	<p>Service Action: Starter Motor. Contact an authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer</p>