

# 46-024: CARB Enhanced Electric Vehicle (EV) and Fuel Cell Electric Vehicle (FCEV) Statement

1/29/2026

[Edit](#) [Clone](#)

46-024

## Subject

CARB Enhanced Electric Vehicle (EV) and Fuel Cell Electric Vehicle (FCEV) Statement

## Whats New Abstract

The repair procedure removes the aftermarket change request, adds GHG label inspection, and directs dealers to open a TCS365 case to order new labels. Warranty codes for inspection and label replacement have been updated.

Certain Battery Electric Vehicles that are subject to California Air Resources Board (CARB) regulations have GHG labels that are missing the CARB Enhanced EV and FCEV Statement.

## Revision

**01/29/2026:** The repair procedure removes the aftermarket change request, adds GHG label inspection, and directs dealers to open a TCS365 case to order new labels. Warranty codes for inspection and label replacement have been updated.

## Condition

The GHG label on affected chassis must be replaced by 02/06/2026 to be in compliance with regulatory standards.

## Chassis Affected

40 US vehicle model year 2025-2026 K270 / K370 / T680 Battery Electric Vehicles manufactured between 11/03/2022 and 11/20/2024 that are subject to CARB regulations.

## Action

### Campaign

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
2. In Service Management, select campaign **46-024** to add it to the case. If the unit is released back into service without performing the repair, make sure to also release the campaign in Service Management.
3. If you are not using Service Management to start repair orders, review SIR for Complete next to the **46-024** campaign code prior to performing this repair.

4. Follow the procedures in the Attachments section to remove and replace the GHG label.

## Warranty

---

Starting on **12/30/2025** Kenworth will pay for parts at dealer net plus applicable mark-up and labor:

- **0.3 hours** of labor to remove and replace the GHG label and take photos of the old and new labels per the bulletin procedures. Select Recommended Repair Code **46-024A**.
- **0.1 hours** of labor to inspect the current GHG label for the required verbiage with no replacement required. Select Recommended Repair Code **46-024B**.
- File an additional claim for extraordinary circumstances. A recommended repair for standard labor must be filed first.

- File the claim within 14 days in accordance with the Warranty Policy.

#### Take-Off Parts Disposition:

- Destroy 30 days after claim is paid

PRWS CLAIM CODING			
<b>Campaign Code:</b>	46-024	<b>Campaign Type:</b>	Field Repair
<b>Claim Category:</b>	Truck	<b>Repair Type:</b>	Proactive
<b>Customer Concern Code:</b>	226	<b>Causal Code:</b>	00
<b>Corrective Action Code:</b>	03	<b>Responsibility Code:</b>	CAMP
<b>Failure Location:</b>	044-015-014	<b>Causal Part:</b>	S53-6198
<b>Supplier Code:</b>	N/A	<b>SRT Code:</b>	<p><b>B25-41A</b>  <b>0.3 hours</b>            Replace GHG label per bulletin procedure.</p> <p><b>B25-41B</b>  <b>0.1 hours</b>            Inspect the current GHG label for required verbiage with no replacement required.</p>

#### Parts

See the 46-024 CARB Enhanced EV and FCEV Statement Repair Procedure in the Attachments section

for instructions on ordering the GHG label.

Quantity	Part Number	Description
1	S53-6198	GHG Label

## Procedure

---

 <b>WARNING!</b>
<p><b>Repair or maintenance procedures may pose a safety risk in limited circumstances. You must read all procedure steps before performing any work and follow all dealership safety procedures or precautions. Failure to comply may result in death, personal injury, or property damage.</b></p>

Please see the Attachments section below for procedures on inspecting, ordering, and removing and replacing the GHG label.

## Attachments

---

CHASSIS LIST

[46-024 KW Chassis List](#)

REPAIR PROCEDURE

[46-024 CARB Enhanced EV and FCEV Statement Procedure](#)

CUSTOMER LETTER

[46-024 KW Customer Letter](#)

# 46-024: CARB Enhanced Electric Vehicle (EV) and Fuel Cell Electric Vehicle (FCEV) Statement

1/29/2026

[Edit](#) [Clone](#)

46-024

## Subject

CARB Enhanced Electric Vehicle (EV) and Fuel Cell Electric Vehicle (FCEV) Statement

## Whats New Abstract

The repair procedure removes the aftermarket change request, adds GHG label inspection, and directs dealers to open a TCS365 case to order new labels. Warranty codes for inspection and label replacement have been updated.

Certain Battery Electric Vehicles that are subject to California Air Resources Board (CARB) regulations have GHG labels that are missing the CARB Enhanced EV and FCEV Statement.

## Revision

**01/29/2026:** The repair procedure removes the aftermarket change request, adds GHG label inspection, and directs dealers to open a TCS365 case to order new labels. Warranty codes for inspection and label replacement have been updated.

## Condition

The GHG label on affected chassis must be replaced by 02/09/2026 to be in compliance with regulatory standards.

## Chassis Affected

126 US vehicle model year 2024-2026 Model 579 / 537 / 520 / 220 Battery Electric Vehicles manufactured between 04/26/2023 and 03/19/2025 that are subject to CARB regulations

## Action

### Campaign

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
2. In Service Management, select campaign **46-024** to add it to the case. If the unit is released back into service without performing the repair, make sure to also release the campaign in Service

## Management.

3. If you are not using Service Management to start repair orders, review SIR for Complete next to the **46-024** campaign code prior to performing this repair.
4. Follow the procedures in the Attachments section to remove and replace the GHG label.

## Warranty

---

Starting on **12/30/2025** Peterbilt will pay for parts at dealer net plus applicable mark-up and labor:

- **0.3 hours** of labor to remove and replace the GHG label and take photos of the old and new labels per the bulletin procedures. Select Recommended Repair Code **46-024A**.
- **0.1 hours** of labor to inspect the current GHG label for the required verbiage with no replacement required. Select Recommended Repair Code **46-024B**.
- File an additional claim for extraordinary circumstances. A recommended repair for standard labor must be filed first.

- File the claim within 14 days in accordance with the Warranty Policy.

#### Take-Off Parts Disposition:

- Destroy 30 days after claim is paid.

PRWS CLAIM CODING			
<b>Campaign Code:</b>	46-024	<b>Campaign Type:</b>	Field Repair
<b>Claim Category:</b>	Truck	<b>Repair Type:</b>	Proactive
<b>Customer Concern Code:</b>	226	<b>Causal Code:</b>	00
<b>Corrective Action Code:</b>	03	<b>Responsibility Code:</b>	CAMP
<b>Failure Location:</b>	044-015-014	<b>Causal Part:</b>	S53-6198
<b>Supplier Code:</b>	N/A	<b>SRT Code:</b>	<b>B25-41A</b> <b>0.3 hours</b> Replace GHG label per bulletin procedure  <b>B25-41B</b> <b>0.1 hours</b> Inspect current GHG label for required verbiage with not replacement required

#### Parts

See the 46-024 CARB Enhanced EV and FCEV Statement Repair Procedure in the Attachments section

for instructions on ordering the GHG label.

Quantity	Part Number	Description
1	S53-6198	GHG Label

## Procedure

---

 <b>WARNING!</b>
<b>Repair or maintenance procedures may pose a safety risk in limited circumstances. You must read all procedure steps before performing any work and follow all dealership safety procedures or precautions. Failure to comply may result in death, personal injury, or property damage.</b>

Please see the Attachments section below for procedures on inspecting, ordering, and removing and replacing the GHG label.

## Attachments

---

CHASSIS LIST

[46-024 PB Chassis List](#)

REPAIR PROCEDURE

[46-024 CARB Enhanced EV and FCEV Statement Procedure](#)

CUSTOMER LETTER

[46-024 PB Customer Letter](#)