

## D074 – 4.4L MILD HYBRID (MHEV) CAR CONFIG FILE (CCF) UPDATE.

### SERVICE ACTION



AFFECTED MODELS	24MY Range Rover, Range Rover Sport
VOLUME AFFECTED	6238 US 816 CAN
REPAIR	A potential concern has been identified on certain 2024 model year Range Rover and Range Rover Sport MHEV vehicles equipped with the 4.4 NC11 P8S engine. The Malfunction Indicator Lamp (MIL) may be illuminated on the vehicle's instrument panel, due to an incorrect car configuration file (CCF). Affected vehicles require a CCF software update to resolve this concern
REPAIR TIME	0.2 hrs + DIDO
CAMPAIGN LAUNCH	Repair bulletin was launched December 18 <sup>th</sup> , 2025
NOTES	Retailers are required to hold all affected new vehicles in their inventory from sale until the repair is available and completed. Sold vehicles are to be repaired at the next service visit All affected VINs are flagged in TOPIx and the warranty portal. BBSS reporting of affected vehicles in retailer inventory is not yet available.