

D062 – DRIVER CONDITION MONITOR INOPERATIVE

SERVICE ACTION



AFFECTED MODELS	26MY Range Rover, Range Rover Sport
VOLUME AFFECTED	147 US (Open VIN when launched to US retailers.)
REPAIR	A concern has been identified on certain 2026 model year Range Rover and Range Rover Sport vehicles where the Driver Condition Monitor (DCM) driver-aid feature is incorrectly turned off and cannot be turned on through the PIVI screen. Affected vehicles require a Car Configuration File (CCF) update to correct the concern.
REPAIR TIME	0.2 - 0.3 hrs + DIDO
CAMPAIGN LAUNCH	The repair bulletin was initially launched to Ports of Entry. It has been republished to retailers on January 7th, 2026, to update certain sold vehicles.
NOTES	Sold vehicles are to be repaired at the next service visit All affected VINs are flagged in TOPIx and the warranty portal. BBSS reporting of affected vehicles in retailer inventory is not yet available.