

ODOR WITHIN THE VEHICLE CABIN

Customer Voice:

- “The interior of the vehicle has a distinct odor.”

Technical Description:

- This odor may be traced to the seat covers on vehicles with light colored leather seat covers.

Status:

- Engineering are currently investigating this concern.
- Initial investigations have linked the odor concern to the anti-soiling treatment applied to light colored leather seats covers.
- **SSM00016** has been published to provide repair guidance.
- Please do not replace any parts unless instructed to do so following the repair instructions.

Range Rover

- 23MY-On Range Rover
- 23MY-On RR Sport

