

**ATTENTION:** Mercedes-Benz Dealer Principals, General Managers, Sales Managers, Service Managers & Parts Managers

## Recall Launch Notification

February 6, 2026

Campaign #	CA DMV #	Description	<b>Update Engine Control Unit Software (Air-to-Fuel Ratio)</b>
2025040001	250401	24P5496502	

### Campaign Details

<b>Total Recall Population</b>	10,605 (Total Population) 9,483 (Initial Population) + 1,122 (Additional Population)	<b>Model(s)/ Platform(s)</b>	C-Class, G-Class, SL (206, 463, 232)
<b>Vehicles in Dealer Inventory</b>	N/A		
<b>Model Year(s)</b>	2023		
<b>Issue</b>	Mercedes-Benz AG, the manufacturer of Mercedes-Benz vehicles, has determined that on certain subject vehicles, the engine control software might not meet current specifications. As a result, the diagnosis routine for monitoring the air-fuel ratio might not be activated as intended and a malfunction in the oxygen sensor could be erroneously detected causing the “check engine” Malfunction Indicator Lamp (‘MIL’) to illuminate.		
<b>What We’re Doing</b>	MBUSA will conduct a voluntary emissions recall. An authorized Mercedes-Benz dealer will update the engine control unit software.		
<b>Remedy</b>	The remedy software is available and can be performed at this time.		
<b>Launch Date</b>	Affected VINs were flagged in VMI as “OPEN” on Friday, June 13, 2025. Additional affected VINs will be flagged as “OPEN” on Friday February 6, 2026.		
<b>Approximate Customer Notification Date</b>	Friday, June 27, 2025 Additional mailings will be sent out on Friday, February 20, 2026.		
<b>Warranty Claim Notice</b>	Please note the campaign will close after the warranty claim has been submitted. This change can take at least one-day to reflect in NetStar VMI.		

**Notice to California Dealers: As required by 13 CCR 2117, a proof of correction (“POC”) certificate showing that the vehicle has been repaired under this recall must be issued by the authorized service facility, and that such a certificate may be required by California as a condition of vehicle re-registration or operation. Please reference this POC in the attached work instructions. Failure to complete this step may result in fines and penalties and lead to customer dissatisfaction.**

While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Care Center at 1-800-FOR-MERCEDES.



# Recall Campaign Bulletin



Mercedes-Benz

June 2025

**Rev. A - February 6, 2026**

TO: ALL MERCEDES-BENZ CENTERS

CAMPAIGN NO.	<b>2025040001</b>
CAMPAIGN DESC.	<b>24P5496502</b>
NHTSA ID	<b>250401</b>
SUBJECT	<b>Update Engine Control Unit Software (Air-to-Fuel Ratio)</b>
MODEL(S)	<b>C-Class, G-Class and SL (206, 463 and 232 platform)</b>
MODEL YEAR(S)	<b>2023</b>
CAMPAIGN POPULATION	<b>10,605 = 9,483 (Initial) + 1,122 (Amendment)</b>

## Campaign Technical Instructions

### Prior to performing this Campaign:

Check the Vehicle Master Inquiry (VMI) to verify this campaign applies to the specific vehicle.

1. Always check for other open campaigns and perform them accordingly!
2. Review the entire campaign bulletin first, and perform the procedures exactly as described.

*California registered vehicles require a Proof of Correction Label and Certificate, according to California Code Regulation Title 13, § 2117 – Proof of Correction Certificate.*

*Non-California dealers may perform the remedy on California registered vehicles, however, please direct those customers to visit their preferred California dealership to receive the Proof of Correction Label and the Certificate after the recall has been completed.*

### **Revision Note(s):**

**- Additional vehicles added to population**

Order No. P-RC-2025040001

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

- Always use the **latest** XENTRY Diagnosis software release with all available add-ons.
- Follow the operation steps exactly as described in XENTRY Diagnosis.
- Use a charger to ensure sufficient power supply to the vehicle's **on-board electrical battery system** (greater than 12.5 V).
- If XENTRY Diagnosis is already connected to the vehicle, start with **Work Procedure Step 2**.

If two or more software updates or SCN codings are performed during a single workshop visit, operation items **02-4762** and **02-5058** may be invoiced **only on one of the workshop orders**.

## Work Procedure

1. Connect XENTRY Diagnosis.
2. Update **Engine Control Unit** software.
  - i** To do so, select menu item "Quick test view → **N3/10 – Motor electronics ‘MED1775’ or ‘MRG2AMG’ for ‘M176’, ‘M177’ or ‘M139’ (ME)** → Adaptations → Control unit update → Updating of the control unit software".
  - i** Then follow the user guidance in XENTRY Diagnosis.
3. Disconnect XENTRY Diagnosis.

## Warranty Information

**i** **Note:** The following allowable labor operation should be used when submitting a warranty claim for this repair:

Damage Code	Operation Number	Description	Labor Time (hrs.)
54 965 02	02-9334	Update <b>N3/10 – Motor electronics (ME)</b> control unit software (with XENTRY Diagnosis connected)	0.1
	02-4762*	Connect/disconnect diagnosis system (XENTRY Diagnosis)	0.1
	02-5058*	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1

\* Invoice operation item only once for each Repair Order (RO).

**i** **Note:** Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.

**i** The following step applies to California dealers only.

Apply Proof of Correction Label (A 000 584 54 13) to area identified in **Figure 1**. Fill in the blank areas of the label. The “**Campaign No.**” for the California Proof of Correction is unique and must be entered as such (**250401**), your “**Dealer Code**”, and the “**Date**” of the repair, using a black permanent marker.

**i** Note: Clean bonding surface prior to affixing label.



**Figure 1**

**i** The following step applies to California dealers only.

Provide the owner with the completed and signed Proof of Correction Certificate (A 000 584 42 14) (**Figure 2**), after you scan a completed form and attach to the RO. The recall number for the California Proof of Correction Certificate is unique and must be entered as such (**250401**).

**Figure 2**

### California Proof of Correction Parts Information

Qty.	Part Name	Part Number
1	Proof of Correction Certificate (CA Dealers Only)	A 000 584 42 14
1	Proof of Correction Label (CA Dealers Only)	A 000 584 54 13

### Warranty Information (California dealers please submit claim on a separate line of the same RO as the campaign)

Damage Code	Operation Number	Description	Labor Time (hrs.)
212CA 00	02-0001	Apply Proof of Correction Label and completed Proof of Correction Certificate	0.1