



SSM 54574 2021-2022 Mustang Mach-E - "Parking Brake Failure, Service Immediately" Displayed In The IPC With DTCs C2008, C2007, C1034, U0293 And/Or U0100 Stored In The ABS Module

Some 2021-2022 Mustang Mach-E vehicles may exhibit a "Parking Brake Failure, Service Immediately" message displayed in the instrument panel cluster (IPC) and diagnostic trouble codes (DTCs) C2007, C2008, C1034, U0293 and/or U0100 stored in the anti-lock brake system (ABS) module. To correct the condition, follow the technical instructions outlined FSA 22P31 (US) or 22B47 (Canada) for an appropriate repair direction.