



Service Bulletin

Bulletin No.: PIT6120C

Date: February, 2026

PRELIMINARY INFORMATION

Subject: Installation of Upfitter Auxiliary Switches (RPO 9L7)

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A / D)	2022		All	All	All	All
Chevrolet	Silverado 1500	2023-2025		All	All	All	All
Chevrolet	Silverado 2500HD	2024-2025		All	All	All	All
Chevrolet	Silverado 3500HD	2024-2025		All	All	All	All
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H / U)	2022		All	All	All	All
GMC	Sierra 1500	2023-2025		All	All	All	All
GMC	Sierra 2500HD	2024-2025		All	All	All	All
GMC	Sierra 3500HD	2024-2025		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	9L7
Condition	A Dealer or Upfitter may be looking for information on installing RPO 9L7 Upfitter Auxiliary Switches. The Upfitter Auxiliary Switches are located under the climate controls in the center of the dash.
Cause	Information not readily available in Service Information (SI.)

Correction

Reference the latest version of GM Upfitter Integration Bulletin 193 or 205 depending on trim level. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

Note: Installation of the Upfitter (AUX) Switches and supporting components are NOT a GM Warranty or PDI covered labor cost. The installation of the switches/components are intended to be performed by the upfitter as a part of the overall vehicle upfit and the labor cost associated with that installation be covered in the upfitter's estimate to its customer. Installation, when performed by a GM dealer, the labor charges associated with that install are the responsibility of the customer/vehicle purchaser.

Version	3
Modified	01/30/2024 - Created on. 09/18/2024 - Updated Model Year 02/14/2025 - Updated Correction Information

