



Service Bulletin

Bulletin No.: PIC6641A

Date: February, 2026

PRELIMINARY INFORMATION

Subject: VCU RPO IVE Software Update Information

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer EV	2025		All	All	All	All

Involved Region or Country	North America, Middle East, Israel, Palestine, Argentina, Brazil, Chile, Colombia, Paraguay
Additional Options (RPO)	IVE
Condition	Some customers may comment on infotainment software related issues and/or request for a radio software update.
Cause	The latest software package is not available in SPS at this time.

Correction

1. Verify radio software version from Setting - System -About - build number is W36E-179.1.2-M174-SQBR6-151.2.
2. If the build number matches the above (W36E-179.1.2-M174-SQBR6-151.2) do not attempt to update the radio software. Attempting a radio software update may fail and cause permanent damage to the radio module.

The USB File Transfer step has been removed from SPS to prevent software/calibration mismatch.

Note: No USB update is required for replacement parts for this vehicle only. Do not attempt to USB update the radio.

Do not replace any parts at this time unless deemed inoperable.

This Preliminary Information will be updated when a resolution is available.

Warranty Information

Labor Operation	Description	Labor Time
3481458*	Verify Radio software version	0.2 Hr.

*This is a unique Labor Operation for Bulletin use only.

Version	2
Modified	1/30/2026 Created. 02/11/2026 Updated Correction.

