



Service Bulletin

Bulletin No.: PIT6486

Date: February, 2026

PRELIMINARY INFORMATION

Subject: Check Engine light Or No Start With DTC P1682

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2024-2026		All	All	All	All

Involved Region or Country	North America
Condition	Some customers may experience a Check Engine Light or no crank, no start with a DTC P1682 setting.
Cause	Internal fault within the Engine Wiring Harness Junction Block.

Correction

Replace the Engine Wiring Harness Junction Block.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4041870	Engine Wiring Harness Junction Block Replacement	Use Published Labor Time

Version	1
Modified	02/16/2026 - Created

