



Service Bulletin

Bulletin No.: PIT6436B

Date: February, 2026

PRELIMINARY INFORMATION

Subject: Malfunction Indicator Lamp (MIL) DTC U0265 That May Set As Current Or Failed In History

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer EV	2024 - 2026		All	All	All	All
Chevrolet	Colorado	2024 - 2026		All	All	All	All
Chevrolet	Equinox EV	2024 - 2026		All	All	All	All
Chevrolet	Silverado EV	2024 - 2026		All	All	All	All
GMC	Canyon	2024 - 2026		All	All	All	All
GMC	Sierra EV	2024-2026		All	All	All	All

Involved Region or Country	United States, Canada, Mexico and South Korea
Condition	Some customers may comment on a Malfunction Indicator Lamp (MIL). The Malfunction Indicator Lamp (MIL) may be intermittent and not be present at the time the vehicle comes in for service. Some technicians may find DTC U0265 That May Set As Current Or Failed In History in the K9 Body Control Module.
Cause	Engineering is currently investigating.

Correction

Do not replace any parts including the K9 Body Control Module or the B174W Front View Camera - Windshield.

Engineering is currently investigating.

In the meantime, please advise customer they may continue to drive the vehicle.

The PI will be updated or replaced with TSB once a determination has been made.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2880578*	Verify DTC U0265 customers concern	0.3 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version	3
Modified	09/19/2025 - Created on. 01/12/2026 - Updated vehicle list. 02/17/2026 - Updated correction.

