



Service Bulletin

Bulletin No.: PIT6485

Date: February, 2026

PRELIMINARY INFORMATION

Subject: Missing Tailgate Assist/Pull Handle

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2026		All	All	All	All
Chevrolet	Silverado 2500	2026		All	All	All	All
Chevrolet	Silverado 3500	2026		All	All	All	All
GMC	Sierra 1500	2026		All	All	All	All
GMC	Sierra 2500	2026		All	All	All	All
GMC	Sierra 3500	2026		All	All	All	All

Involved Region or Country	North America
Condition	A technician (during PDI) or a customer may comment that the tailgate assist handle was not included at the time the vehicle was delivered, see picture below.
Cause	The assist handle has changed from an included part of RPO QK2 (Mult Flex or MultiPro tailgate) to a stand-alone option, RPO TGH. To get the handle, RPO TGH must be ordered for the handle to be included.



6714845

Correction

Do not install an assist handle on a vehicle that is missing the handle unless the vehicle is equipped with RPO TGH.

The assist handle has changed from an included part of RPO QK2 (MultiFlex or MultiPro tailgate) to a stand-alone option, RPO TGH. To get the handle, RPO TGH must be ordered.

RPO TGH is tied to RPO CGN, any truck with RPO CGN can get RPO TGH. It is no longer tied to the QK2 gate. The warranty labor code for the assist handle 1414930 will be restricted to RPO: TGH only on 2026 and later pickups.

If a customer desires to have the handle, they can purchase the assembly through the parts department. This is a customer pay (non-warranty) item. Any warranty claims submitted for the tailgate handle that doesn't have the RPO: TGH will be charged back.

Version	1
Modified	02/16/2026 - Created on

