

[26-BE-001H-1 - Horn Assembly Replacement \(Z09\)_\(Posted 02.17.26\).pdf](#)

[Warranty Extension Z09 - Inoperative Horn - Dealer Notification \(posted 02.17.26\).pdf](#)

Hyundai Motor America (HMA) has re-launched Warranty Extension Z09 for the Inoperative Horn Assembly Replacement.

This TSB supersedes 26-BE-001H to add Santa Fe (TMA) and Santa Fe Hybrid (TMA HEV) to the Applicable Vehicles, Parts Information and Warranty Information.

A. Affected Vehicles:

- Certain 2021-22MY Santa Fe Hybrid produced 12/18/2020 – 09/14/2023
- Certain 2022-23MY Santa Fe Plug-in Hybrid produced 05/13/2021 – 09/14/2023
- Certain 2021-23MY Santa Fe (TMA) produced 10/30/2020 – 12/29/2023 (added for this re-launch)
- Certain 2023MY Santa Fe Hybrid (TMA HEV) produced 10/10/2022 – 12/29/2023 (added for this re-launch)

****VIN Identification:** Use the 'Vehicle Information' screen in WebDCS under the 'Extended Factory Warranty' section to determine warranty extension applicability.

B. Warranty Extension Description:

Some vehicles may have an inoperable horn that may be caused by foreign substances causing internal parts to oxidize.

Hyundai is extending the warranty coverage for the horn replacement under this condition to 10 years or 120,000 miles from the date of original retail delivery or date of first use (whichever occurs first) and is valid for original and subsequent owners.

If a horn needs to be replaced, follow the instructions within this **Technical Service Bulletin (TSB) 26-BE-001H-1** to install the latest design.

Please note that any vehicles under 10 years/120,000 miles are covered by this TSB, even if vehicle is with original warranty of 5 years/60,000 miles.

C. Parts Ordering/Information:

A. High & Low Pitch Horns - Parts may be ordered through the normal WebDCS process.

- a. VIN required: A valid warranty extension Z09 VIN will be required to order both part numbers.

D. Warranty Extension Document(s):

1. TSB 26-BE-001H-1; supersedes TSB 26-BE-001H

- a. Available on [Hyundaidealer.com](#) > Service > HMA Tech Info > TSB

2. Dealer Notification; supersedes existing document

- a. Available on [Hyundaidealer.com](#) > Service > HMA Tech Info > Service News

E. Action Required:

1. Confirm VIN eligibility for warranty extension via WebDCS.
2. **Follow TSB 26-BE-001H-1** for service procedure to replace the high & low pitch horn assemblies if the horn is inoperable.
3. **Submit under the 'Campaign' claim entry screen** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.

Thank you for your patience and understanding.

Warranty Campaign Team

Hyundai Motor America