

**In-Vehicle / In-App Communication
Service Action Notification-Reminder
5 Feb 2026**

Title	Text	Short Text	Pop-Up
Service Action: Front Electric Drive Unit	<p>A manufacturing defect in a bearing of the electronic drive unit could result in bearing damage. This is caused by an unusual acoustic signal in the area of the drive unit. The bearing could fail completely at a later stage, which will be displayed to you by means of a red Check Control message. In this case, the driver is asked to call BMW Roadside Assistance.</p> <p>Contact authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.</p>	<p>Service Action: Front Electric Drive Unit. Contact an authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer</p>	<p>Service Action: Front Electric Drive Unit. Contact an authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer</p>