

GENERAL MOTORS
DCS7441
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 25, 2026
Subject: N252540910 - Service Update
Engine Replacement
Models: 2026 Buick Enclave

General Motors is releasing Service Update N252540910 today.

The below vehicle was placed on stop delivery December 12, 2025. Once the service procedure contained in the attached bulletin has been performed on the vehicle, the vehicle is released from stop delivery and the vehicle can be delivered to the customer.

BAC

VIN

115082 or 286194

5GAEVBKS4TJ230447

Shipments of part number 11604736 are arriving this week. If parts are not immediately available through CCA please escalate to a SPAC order so it will open to SPRINT.

END OF MESSAGE

Service Update

N252540910 Engine Replacement



Release Date: February 2026

Revision: 00

Attention: PLEASE NOTE: There are only 4 vehicles involved in this field action. The VINs are below:

1GNEVLKS2TJ230474

1GKENPKS1TJ230423

1GKENLKS7TJ230483

5GAEBKBS4TJ230447

Vehicles involved in this recall were placed on stop delivery December 12, 2025. Once the service procedure contained in this bulletin has been performed on the vehicle, the vehicle is released from stop delivery and the vehicle can be delivered to the customer.

All involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in this bulletin has been performed on the vehicle.

This service update involves vehicles in dealer inventory only and will expire February 28, 2027.

Investigate Vehicle History (IVH) in the GM Global Warranty Management system MUST always be checked to confirm vehicle involvement and MUST be in OPEN status prior to beginning any required inspections and/or repairs. DO NOT use Service Information with VIN search, as it will not verify the VIN eligibility for field actions.

Make	Model	Model Year	
		From	To
Buick	Enclave	2026	2026
Chevrolet	Traverse	2026	2026
GMC	Acadia	2026	2026

This service update should be performed on vehicles in dealer inventory only. Investigate Vehicle History (IVH) in the GM Global Warranty Management system MUST always be checked to confirm vehicle involvement and MUST be in OPEN status prior to beginning any required inspections and/or repairs. DO NOT use Service Information with VIN search, as it will not verify the VIN eligibility for field actions.

Condition	Certain vehicles listed above may have a condition in which a quality issue with the engine was identified.
Correction	Dealers will replace the engine.

Service Update

N252540910 Engine Replacement



Parts

Quantity	Part Name	Part No.
1	Engine	12744958
1	Air Conditioning Compressor and Condenser Hose Seal - Large	13579646
1	Air Conditioning Compressor and Condenser Hose Seal - Small	13579648
1	Catalytic Converter Gasket	26381263
4	Catalytic Converter Nut	15032594
4	Drivetrain and Front Suspension Cradle Bolt	11547841
1	Exhaust System Intermediate Gasket	26416290
3	Front Wheel Drive Intermediate Shaft Bracket Bolt	11588728
2	Front Wheel Drive Shaft Nut	11612295
2	Front Wheel Drive Shaft Retaining Ring	90223082
2	Front Wheel Drive Shaft Washer	11604736
1	Fuel Feed Intermediate Pipe	12728652
1	Fuel Injector Nozzle Housing Seal	12737839
1	Fuel Pump Housing Seal	12645181
1	Intake Manifold Gasket	12697072
1	Oil Filter	12735608
1	Oil Level Indicator Tube Seal	12670252
1 (AWD only)	Power Transfer Unit Half Shaft Seal	19132944
1 (AWD only)	Power Transfer Unit Half Shaft Retainer Clip	19132950
1 (AWD only)	Power Transfer Unit Propeller Shaft Retainer	23432713
2 (AWD only)	Power Transfer Unit Propeller Shaft Seal	23321677
1 (AWD only)	Propeller Shaft to Differential Carrier Interface Retainer	23432713
1	Turbocharger Air Inlet Adapter Seal	12701703
1	Turbocharger Coolant Feed and Return Pipe Gasket	12697763
1	Turbocharger Coolant Feed and Return Pipe Gasket	12669556
1	Turbocharger Exhaust Pipe Gasket	12739848
1	Turbocharger Heat Shield	12728638
4	Turbocharger Nut	11612078
2	Turbocharger Oil Feed Pipe Gasket	12669556
1	Water Outlet Seal	12695721
6	Engine Oil Dexos1 Gen 3 0W-20	19432331
5	Engine Coolant DEX-COOL	12346290

Reminder: Parts may be removed from SPRINT and Retail Inventory Management (RIM) and be non-returnable. Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9108293	Engine Replacement AWD FWD Add: Recover/Recharge R-1234yf A/C System	13.8 12.9 1.2	ZFAT	N/A
9108294	Floor Plan Reimbursement – NEW INVENTORY ONLY	N/A	ZFAT	*

Please Note: The above labor time(s) are published direct from the Labor Time Guide.

Note: To avoid having to “H” route the floor plan transaction for approval, it must be submitted prior to the repair transaction.

Service Update

N252540910 Engine Replacement



Floor Plan Reimbursement – NEW INVENTORY ONLY

* For vehicles eligible for floor plan reimbursement, the amount should be submitted in Net Item/Miscellaneous. This amount should represent the product of the vehicle's average daily interest rate (see table below) multiplied by the actual number of days the vehicle was in dealer inventory and not available for sale. This reimbursement is limited to the number of days from the date of the stop delivery notification (December 12, 2025) to the date the repair is completed, and the vehicle is ready for sale (not to exceed 74 days).

Vehicle	Floor Plan Reimbursement Amount
	USA
2026 Buick Enclave	\$19.07
2026 Chevrolet Traverse	\$16.68
2026 GMC Acadia	\$18.38

Service Procedure

Replace the engine. Refer to *Engine Replacement* in SI.

Dealer Responsibility

Dealers must take the steps necessary to ensure that the service update correction has been made to all involved vehicles in dealer inventory before selling or dealer-trading the vehicle, but no later than the end date as noted in the Attention box.

All new, used, GM Certified Pre-Owned (CPO), courtesy transportation vehicles, dealer shuttle vehicles, CarBravo, etc. in dealers' possession and subject to this field action must be held and inspected/repared per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Pre-Owned (CPO) vehicles currently in the dealers' inventory within the SHIFT Digital system will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the SHIFT Digital system, or once again be used in the Courtesy Transportation Program.

Dealer Reports – For USA and Export

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support
Voluntary Technician
Certification**