

# V O L V O

## Volvo Car USA LLC

## Technical Journal

Technical Journal Title Coolant Pump Coolant Mix Residue		Ref. No. TJ 36923.9.0	
Issuer (Dept.) Technical Service		Issue Date 2/5/26	Status Date 2/13/26
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 2621	
Function Description Coolant pump, complete		Page Page 1 of 3	

### Attachment

File Name	File Size
TJ_36923_1.pdf	0.1952 MB

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

### DESCRIPTION:

\*Title and attachment updated, photo requirement removed.

If the coolant pump has a small sign of green/white coolant mix (see example as in attached picture TJ\_36923\_1.pdf) without a DTC set, follow advice under "Service".

### CSC Customer Symptom Codes

Code	Description
EZ	Warning lights and chimes/Coolant level indication/no indication
Q8	Engine cooling/Coolant leakage

### DTC Diagnostic Trouble Codes

### Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224	L1	BL1KERS					2022-2025		-	202122-999952
225	06	B06KERS					2023-9999		-	202222-999952
227	L1	BL1KERS					2023-9999		-	202222-999952
236	06	B06KERS					2022-9999		-	202122-999952
238	06	B06KERS					2022-9999		-	202122-999952
238	L1	BL1KERS					2022-9999		-	202123-999952
246	06	B06KERS					2022-9999		-	202122-999952
246	L1	BL1KERS					2022-9999		-	202122-999952
246	M1	BM1KERS					2025-9999		-	202417-999952
256	06	B06KERS					2023-9999		-	202222-999952

## Technical Journal 36923.9.0

---

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256	L1	BL1KERS					2023-9999		-	202222-999952
256	M1	BM1KERS					2025-9999		-	202407-999952
536	K9	BK9KERS					2023-9999		-	202222-999952
536	L1	BL1KERS					2023-9999		-	202222-999952

### **SERVICE:**

*\*No replacement of the coolant pump is allowed without a genuine customer symptom e.g. low coolant warning message.*

If there are traces of coolant seen after engine shut off with no other symptoms (see example as in attached picture TJ\_36923\_1.pdf), this is normal and should not be seen as an indication to replace the coolant pump.

### **Warranty claim info:**

No warranty claim is accepted for this TJ.

**Concerned Part No:** 32252604; 32252284; 32382367; 32382368; 32441161

### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 2621.

**To view TJ attachments continue to next page. This TJ has three attachments.**

TJ 36923

