

WST8 Workshop Campaign – Reworking Rear Lid

WST8 Workshop Campaign - Reworking Rear Lid

ID Number	WST8
Model(s)	911 GT3 (992)
Model Year(s)	2025 - 2026
Number of Affected Vehicles	225
VIN List	Attached below
Issue Description	<p>There is a possibility that the fastening nuts on the rear lid on the affected vehicles were not tightened to the specified tightening torque.</p> <p>If this is the case, it can cause noises with the rear lid while driving.</p> <p>To prevent this from happening, the fastening nuts on the rear lid must be tightened to the prescribed tightening torque.</p>
What should Porsche Centers do?	<p>Please arrange for the measure to be carried out on affected vehicles as soon as possible.</p> <p>As of the time of this posting (2/4/26) the remedy is immediately available.</p>
Parts Status	Status 0 - No parts needed
TI	WST8

Warranty processing

Validity:

The present workshop campaign is carried out by the date maintained in PCSS and then closed.

Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Code	WST8 66 000
-------------	-------------

WST8 Workshop Campaign – Reworking Rear Lid

Repair Code	1
Labor time	13 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Attachments

1. [VIN_List_Report_WST8_2026-02-04_V4.xlsx](#)