

WSS0 Workshop Campaign - Check the return line (Porsche Dynamic Chassis Control) and replace it if necessary

WSS0 Workshop Campaign - Check the return line (Porsche Dynamic Chassis Control) and replace it if necessary

ID Number	WSS0
Model(s)	911 Carrera GTS (992) 911 Carrera 4 GTS (992) 911 Turbo S (992)
Model Year(s)	2025 - 2026
Number of Affected Vehicles	103
VIN List	Attached below
Issue Description	<p>Due to a manufacturing error, there is a possibility that the return line of the PDCC system is leaking in the area where it adjoins the PDCC pump.</p> <p>This may lead to oil loss and consequently to the deactivation of the PDCC system. Deactivation is warned in yellow on the instrument cluster; the vehicle remains ready to drive.</p> <p>To prevent this from happening, the return line (PDCC) must be replaced on the affected vehicles.</p>
What should Porsche Centers do?	<p>Please arrange for the measure to be carried out on affected vehicles as soon as possible.</p> <p>As of the time of this posting (2/11/26) the remedy is immediately available.</p>
Parts Status	Status 1 - Order as needed
TI	WSS0

WSS0 Workshop Campaign - Check the return line (Porsche Dynamic Chassis Control) and replace it if necessary

Warranty processing

Validity:

The present workshop campaign is carried out by the date maintained in PCSS and then closed. Please note that warranty claims can only be processed up to this date.

Scope 1: Checking the return line (PDCC)

Damage Code	WSS0 66 000
Repair Code	1
Labor time	88 TU

Scope 2: Checking and replacing return line (PDCC)

Damage Code	WSS0 66 000
Repair code	2
Labor time	304 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Attachments

1. [VIN_List_Report_WSS0_2026-02-11_V4.xlsx](#)