

Technical Service Bulletin

Topic	Connectivity Issue – 2.4 GHz Wi-Fi Browsing Not Possible via Vehicle Hotspot
Market area	Bentley: worldwide (2WBE),China 796 VW Import Comp. Ltd (Vico), Beijing (6796)
Brand	Bentley
Transaction No.	2080625/1
Level	EH
Status	Released for publishing
Release date	Feb 2, 2026

New customer code

Object of complaint	Complaint type	Position
information, navigation, communication, entertainment -> cell phone functions, customer portal, applications	functionality	
information, navigation, communication, entertainment -> controlling infotainment with buttons, controls, screen	functionality	

Vehicle data

Continental GT/GTC/Flying Spur

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
Z23*	2026	E		*	*	*
Z24*	2026	E		*	*	*
Z32*	2026	E		*	*	*

Bentayga

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2026	E		*	*	*

Documents

Document name
master.xml

Condition

When connected to the vehicle hotspot using the 2.4 GHz Wi-Fi band, web browsing on mobile devices may not function.

This condition does not affect Android Auto or Apple CarPlay, and the 5 GHz Wi-Fi band operates normally.



Customers are advised to use the 5 GHz connection for uninterrupted service.

Technical Background

The system recovers automatically after an ignition cycle.

No hardware fault is present.

Production Solution

Not applicable

Service

NOTICE

Do NOT replace any components.

NOTICE

Please raise a full technical DISS query and escalate it to second-level review by the Electrical TM.

Guidance to Customer

1. Activate the vehicle's Wi-Fi Hotspot.
2. On your phone, open the Wi-Fi settings. You should see two available networks:
 - 2.4 GHz
 - 5 GHz
3. You can connect to either network.
4. If you experience an issue where you are connected to the 2.4 GHz network but have no internet access, switch to the 5 GHz network.
5. This should resolve the connectivity issue.
6. If the issue persists, perform an ignition cycle and confirm functionality.

Warranty

No component replacement is authorised for this issue.

This is a software-related condition that resolves automatically.

Warranty claims for part replacement will not be accepted.