



Service Bulletin

Bulletin No.: PIC6647

Date: February, 2026

PRELIMINARY INFORMATION

Subject: IP Storage Compartment May Not Release

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2026		September 19 2025	November 11 2025	All	All

Involved Region or Country	North America
Condition	Some customers may comment that the IP storage compartment may not open on the first press of the release button. The IP storage compartment may have a delay when opening, or it may require multiple presses of the switch until the IP storage compartment door will open.
Cause	This concern may be caused by the contacts in the switch not making good contact.

Correction

To correct this concern, dealerships are to replace the IP compartment door release switch.

Note: This PI will be updated or changed to a bulletin as more information becomes available.

Parts Information

Use the vehicle identification number (VIN), SI, and the GM Electronic Parts Catalog to determine the correct part to order.

Version	1
Modified	02/27/26 - Created on

