



## **SSM 54614 2020-2024 Explorer 2.3L EcoBoost, 2020-2026 Explorer/Police Interceptor Utility/Aviator 3.0L/3.3L - Fuel Tank/Fuel Pump And Sender Unit Removal And Installation WSM Updates**

Some 2020-2024 Explorer vehicles equipped with a 2.3L engine and 2020-2026 Explorer/Police Interceptor Utility/Aviator vehicles equipped with a 3.0/3.3L engine may require various repairs associated with the fuel tank and/or fuel pump and sender unit. Workshop Manual (WSM), Section 310-00 > Removal and Installation for the fuel tank and fuel pump and sender unit have been revised to eliminate the need to remove the driveshaft as part of the service procedure. Labor times have also been updated to reflect this WSM revision.