

RATTLE TYPE NOISE FROM LOWER STEERING COLUMN AREA

Customer Voice:

- “There is a rattle noise turning slightly over uneven road surfaces.”

Technical Description:

- This may be caused by the steering column flexible coupling.

Status:

- Engineering are currently investigating this concern.
- SSM000020 has been published to provide repair guidance.
- Please do not replace any parts unless instructed to do so following the repair instructions.
- Please report repair details via EPQR for actions correcting the concern as requested in the SSM.

Range Rover

- 22MY-On Range Rover (L460)
- 23MY-On RR Sport

