

CE031: MX Component Specific Emissions Warranty for EMY2022 PACCAR MX-11 and MX-13 Engines

2/26/2026

 [Edit](#)  [Clone](#)

CE031: MX Component Specific Emissions Warranty for EMY2022 PACCAR MX-11 and MX-13 Engines

Whats New Abstract

Fuel Injection Pump part number 2344776PEX for MX-13 engines has been added to this warranty policy.

Introduction

U.S. & Canada Federal emissions regulates that the warranty coverage is a period of ten (10) years or 435,000 miles/700,000 km/22,000 engine hours, whichever comes first, from the original warranty registration date, for these specific components on the EMY2022 PACCAR MX-11 and MX-13 Engines.

PACCAR has implemented the extension and it is effective retroactively, unless the part is listed as ineligible for reimbursement below.

Revision

02/26/2026 – Fuel Injection Pump part number 2344776PEX for MX-13 engines has been added to this warranty policy.

01/27/2026 – DPF Delta Pressure Sensor part number 2200138 for MX-11 engines has been added to this warranty policy.

08/19/2025 – Fuel Injection Pump Part Number 2185361PE for MX-13 engines has been added to this warranty policy.

03/10/2025 – multiple Injector part numbers added to this warranty policy.

12/19/2024 – DPF Delta Pressure Sensor part number 2200138PE for MX-13 engines has been added to this warranty policy.

04/02/2024 – Added fuel injector for PACCAR MX-11.

Condition

Units that have coverage under this warranty will be identified in the Service Information Record (SIR):

Sales Code	Coverage Description
9202162	EW: MX Emissions 10yr/435K Miles (700K KM) – Engine MY2022

Submit a long-form warranty claim through PRWS, using the applicable claim type shown in the chart below, for any repair that meets the requirements of this bulletin. If the repair falls under campaign E290, file a claim using appropriate quick claim code from campaign E290. Please ensure the correct VIN number is selected and that all claim filing requirements are met.

Please use the following coding when submitting your warranty claim:

PPD Part Number	Part Description	Claim Type	Failure Location
2314737(PEX)	Injector, MX-13, EPA21	Engine	044-004-001
2314736(PEX)	Injector, MX-11, EPA21	Engine	044-004-001
2383578(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2383579(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2394547(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2394548(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2403775(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2403776(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2403200(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2403201(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2403777(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2403778(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2423651(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2423652(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2423653(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2423654(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2426853(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2426854(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2426855(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2426856(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2429854(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2429855(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2428773(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2428774(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2452061(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2452062(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2460409(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2460410(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2460411(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2460412(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2460413(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2460414(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2185361(PE)	Fuel Injector Pump, MX-11, MX-13, EPA21	Engine	044-003-218
2200138	DPF Delta Pressure Sensor, MX-11, MX-13, EPA21	Engine	043-006-007
2344776PEX	Fuel Injection Pump, MX-13	Engine	044-003-218

For retroactive payments please file a long-form claim, and populate parts and labor costs to the sublet fields. Please make sure to attach an invoice and receipt to the claim to document the repair and payment made.

Warranty

The emissions warranty will cover the repair costs for any failure of an emissions-related part described in this bulletin that results under normal use and service, caused by a warrantable failure, which must be

the result of a defect in material and/or factory workmanship. Reimbursement will include:

- Parts
- Labor
- Consumables (when not reusable)

Please submit a claim using one of the following claim types:

- For DEF sensor claims, file a TRUCK claim.
- For all other engine-related claims, file an ENGINE claim

PROACTIVE REPAIRS ARE NOT COVERED BY THIS PROGRAM.

Towing will only be covered if 'engine' emission component failure occurs within the base engine period of 24 months/250,000 miles/6,250 hours. Outside of base engine coverage, towing and travel are

excluded. PACCAR will pay for reasonable labor costs for engine removal and reinstallation when necessary to repair a warrantable failure.

The emissions warranty is retroactive and applies to qualifying warrantable failures that customers have

already had repaired at their expense.

Components that qualify for coverage on EMY2022 PACCAR MX-11 and MX-13 Engines:

Engine Model Year	PPD Part Number	Part Description
2022 (MX-13)	2314737PEX ⁽¹⁾	Fuel Injector
	2383579PEX ⁽¹⁾	
	2394548PEX ⁽¹⁾	
	2403776PEX ⁽¹⁾	
	2403201PEX ⁽¹⁾	
	2403778PEX ⁽¹⁾	
	2423652PEX ⁽¹⁾	
	2423654PEX ⁽¹⁾	
	2426854PEX ⁽¹⁾	
	2426856PEX ⁽¹⁾	
	2429855PEX ⁽¹⁾	
	2428774PEX ⁽¹⁾	
	2452062PEX ⁽¹⁾	
	2460410PEX ⁽¹⁾	
	2460412PEX ⁽¹⁾	
	2460414PEX ⁽¹⁾	
2022 (MX-11)	2314736PEX ⁽¹⁾	Fuel Injector
	2383578PEX ⁽¹⁾	
	2394547PEX ⁽¹⁾	
	2403775PEX ⁽¹⁾	
	2403200PEX ⁽¹⁾	
	2403777PEX ⁽¹⁾	
	2423651PEX ⁽¹⁾	

	2423653PEX ⁽¹⁾ 2426853PEX ⁽¹⁾ 2426855PEX ⁽¹⁾ 2429854PEX ⁽¹⁾ 2428773PEX ⁽¹⁾ 2452061PEX ⁽¹⁾ 2460409PEX ⁽¹⁾ 2460411PEX ⁽¹⁾ 2460413PEX ⁽¹⁾	
2022 (MX-13)	2185361PE ⁽¹⁾ 2344776PEX ⁽²⁾	Fuel Injection Pump
2022 (MX-11 and MX-13)	2200138 ⁽¹⁾	DPF Delta Pressure Sensor
⁽¹⁾ Part added in a previous update. ⁽²⁾ Part added in latest update.		

Attachments

[U.S. Customer Letter](#)

[Spanish Customer Letter](#)

[Canada English Customer Letter](#)

[Canada French Customer Letter](#)

[Chassis List](#)

CE031: MX Component Specific Emissions Warranty for EMY2022 PACCAR MX-11 and MX-13 Engines

2/26/2026

 [Edit](#)  [Clone](#)

Whats New Abstract

Fuel Injection Pump part number 2344776PEX for MX-13 engines has been added to this warranty policy.

Introduction

U.S. & Canada Federal emissions regulates that the warranty coverage is a period of ten (10) years or 435,000 miles (700,000 km) or 22,000 engine hours from the original warranty registration date, whichever comes first, for these specific components on the EMY2022 PACCAR MX-11 and MX-13 Engines. PACCAR has implemented the extension and it is effective retroactively unless the part is listed as ineligible for reimbursement below.

Revision

02/26/2026 – Fuel Injection Pump part number 2344776PEX for MX-13 engines has been added to this warranty policy.

01/27/2026 – DPF Delta Pressure Sensor part number 2200138 for MX-11 engines has been added to this warranty policy.

08/19/2025 – Fuel injector pump part number 2185361 for MX-13 engines has been added to this warranty policy.

03/26/2025 – Fuel injector part numbers for MX-11 and MX-13 engines have been added to this warranty policy.

12/19/2024 – DPF Delta Pressure Sensor part number 2200138PE for MX-13 engines has been added to this warranty policy.

04/02/2024 – Fuel injector part number 2314736PEX for MX-11 engines has been added to this warranty policy.

08/30/2023 – Fuel injector part number 2314737PEX for MX-13 engines has been added to this warranty policy.

Condition

Units that have coverage under this warranty will be identified in Service Information Record

(SIR):

Sales Code	Coverage Description
9480836	EW: MX Emissions 10yr/435K Miles (700K KM) - Engine MY2022

PPD Part Number	Part Description	Claim Type	Failure Location
2314737(PEX)	Injector, MX-13, EPA21	Engine	044-004-001
2314736(PEX)	Injector, MX-11, EPA21	Engine	044-004-001
2383578(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2383579(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2394547(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2394548(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2403775(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2403776(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2403200(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001
2403201(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004-001
2403777(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004-001

2403778(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004- 001
2423651(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004- 001
2423652(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004- 001
2423653(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004- 001
2423654(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004- 001
2426853(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004- 001
2426854(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004- 001
2426855(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004- 001
2426856(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004- 001
2429854(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004- 001
2429855(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004- 001
2428773(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004- 001
2428774(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004- 001
2452061(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004- 001
2452062(PEX)	Fuel	Engine	044-004-

	Injector, MX-13, EPA21		001
2460409(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004- 001
2460410(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004- 001
2460411(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004- 001
2460412(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004- 001
2460413(PEX)	Fuel Injector, MX-11, EPA21	Engine	044-004- 001
2460414(PEX)	Fuel Injector, MX-13, EPA21	Engine	044-004- 001
2185361(PE)	Fuel Injector Pump, MX- 11, MX-13, EPA21	Engine	044-003- 218
2200138	DPF Delta Pressure Sensor, MX- 11, MX-13, EPA21	Engine	043-006- 007
2344776PEX	Fuel Injection Pump, MX- 13	Engine	044-003- 218

- For reimbursement of past repairs, unless noted above as not eligible, file a claim in accordance with the warranty procedure manual.
- Attach an invoice and receipt to the claim to document the repair and payment made.
- In addition, attach receipt of reimbursement made to customer for the initial invoice/costs of repair.
- Retroactive claims without these items will be denied.

Warranty

The emissions warranty will cover the repair costs for any failure of an emissions-related part described in this bulletin that results under normal use and service, caused by a warrantable failure, which must be

the result of a defect in material and/or factory workmanship. Reimbursement will include:

- Parts
- Labor
- Consumables (when not reusable)

**NOTE**

Cummins-powered chassis do not have Extended Emissions Coverage under this bulletin.

PROACTIVE REPAIRS ARE NOT COVERED BY THIS PROGRAM

Towing will only be covered if 'engine' emission component failure occurs within the base engine period of 24 months/250,000 miles/6,250 hours, whichever comes first. Outside of base engine coverage, towing and travel are excluded.

PACCAR will pay for reasonable labor costs for engine removal and reinstallation when necessary to repair a warrantable failure.

The emissions warranty is retroactive and applies to qualifying warrantable failures that customers have

already had repaired at their expense.

Components that qualify for coverage on MY2022 PACCAR MX Engines:

2022 (MX-13)	2314737PEX ⁽¹⁾	Fuel Injector
	2383579PEX ⁽¹⁾	
	2394548PEX ⁽¹⁾	
	2403776PEX ⁽¹⁾	
	2403201PEX ⁽¹⁾	
	2403778PEX ⁽¹⁾	
	2423652PEX ⁽¹⁾	
	2423654PEX ⁽¹⁾	
	2426854PEX ⁽¹⁾	
	2426856PEX ⁽¹⁾	
	2429855PEX ⁽¹⁾	
	2428774PEX ⁽¹⁾	
	2452062PEX ⁽¹⁾	
	2460410PEX ⁽¹⁾	
	2460412PEX ⁽¹⁾	
	2460414PEX ⁽¹⁾	
2022 (MX-11)	2314736PEX ⁽¹⁾	
	2383578PEX ⁽¹⁾	
	2394547PEX ⁽¹⁾	
	2403775PEX ⁽¹⁾	
	2403200PEX ⁽¹⁾	
	2403777PEX ⁽¹⁾	
	2423651PEX ⁽¹⁾	
	2423653PEX ⁽¹⁾	
	2426853PEX ⁽¹⁾	
	2426855PEX ⁽¹⁾	
	2429854PEX ⁽¹⁾	
	2428773PEX ⁽¹⁾	
	2452061PEX ⁽¹⁾	
	2460409PEX ⁽¹⁾	
	2460411PEX ⁽¹⁾	
	2460413PEX ⁽¹⁾	
2022 (MX-13)	2185361PE ⁽¹⁾ 2344776PEX ⁽²⁾	Fuel Injection Pump
2022 (MX-11 and MX-13)	2200138 ⁽¹⁾	DPF Delta Pressure Sensor
⁽¹⁾ Component added in previous Extended Warranty Coverage update. ⁽²⁾ Additional component added to Extended Warranty Coverage.		

If there is a failure on any of the parts listed above, submit a warranty claim through PACCAR Registration and Warranty System (PRWS). Ensure the correct VIN number and Causal Part removed from the vehicle are on the submitted claim.

Attachments

[CE031 PB Chassis List](#)

[CE031 PB US Customer Letter](#)

[CE031 PB US Customer Letter - Spanish](#)

[CE031 PB Canadian Customer Letter](#)

[CE031 PB Canadian Customer Letter - French](#)

Date à être déterminée

Objet : CE031 Garantie relative aux émissions spécifiques des composantes MX pour moteurs MX-11 et MX-13 EMY2022 de PACCAR

Date d'expiration : Aucune



Cet avis concerne votre véhicule. Votre (vos) NIV(s) se trouve(ent) au recto ou au verso de la présente.

Cher client Kenworth,

Nous vous faisons parvenir cet avis conformément aux exigences de la Loi canadienne relative à la protection de l'environnement (1999).

Il ne s'agit pas d'un rappel ni d'une campagne. Vous n'avez pas à prendre rendez-vous avec votre concessionnaire sauf si votre véhicule présente un problème.

Nous vous faisons parvenir cette lettre afin de vous informer que Kenworth Truck Company a prolongé la couverture de garantie de certaines composantes relatives aux émissions installées sur votre (vos) véhicule(s). Votre (vos) véhicule(s) comporte(nt) l'une ou plusieurs pièce(s) listée(s) à la présente. Aucune action n'est requise de votre part.

La couverture de garantie relative aux émissions pour les composantes listées dans le tableau ci-après a été prolongée à 10 ans/700 000 km, ou 22 000 heures de fonctionnement du moteur à compter de la date d'enregistrement de la garantie originale, selon la première éventualité.

Tableau 1 – Pièces couvertes par la couverture de garantie prolongée (code EWC 9202162)

Nom de la pièce	No. de la pièce	Résultat de la défectuosité
Injecteur de carburant (MX-13, EPA21)	2314737PEX ⁽¹⁾ 2383579PEX ⁽¹⁾ 2394548PEX ⁽¹⁾ 2403776PEX ⁽¹⁾ 2403201PEX ⁽¹⁾ 2403778PEX ⁽¹⁾ 2423652PEX ⁽¹⁾ 2423654PEX ⁽¹⁾ 2426854PEX ⁽¹⁾ 2426856PEX ⁽¹⁾ 2429855PEX ⁽¹⁾ 2428774PEX ⁽¹⁾ 2452062PEX ⁽¹⁾ 2460410PEX ⁽¹⁾ 2460412PEX ⁽¹⁾ 2460414PEX ⁽¹⁾	Une performance insuffisante de l'injecteur de carburant peut générer une régénération insuffisante ainsi qu'une accumulation importante de suie sur le filtre à particules diesel à la suite d'une combustion inégale du carburant.

Injecteur de carburant (MX-11 EPA21)	2314736PEX ⁽¹⁾ 2383578PEX ⁽¹⁾ 2394547PEX ⁽¹⁾ 2403775PEX ⁽¹⁾ 2403200PEX ⁽¹⁾ 2403777PEX ⁽¹⁾ 2423651PEX ⁽¹⁾ 2423653PEX ⁽¹⁾ 2426853PEX ⁽¹⁾ 2426855PEX ⁽¹⁾ 2429854PEX ⁽¹⁾ 2428773PEX ⁽¹⁾ 2452061PEX ⁽¹⁾ 2460409PEX ⁽¹⁾ 2460411PEX ⁽¹⁾ 2460413PEX ⁽¹⁾	Une performance insuffisante de l'injecteur de carburant peut générer une régénération insuffisante ainsi qu'une accumulation importante de suie sur le filtre à particules diesel à la suite d'une combustion inégale du carburant.
Pompe d'injection de carburant (MX-13, EPA21)	2185361PE ⁽¹⁾ 2344776PEX ⁽²⁾	Les défaillances des pompes d'injection de carburant qui entraînent une surveillance inexacte des gaz d'échappement peuvent compromettre l'efficacité du système SCR et affecter les émissions d'oxyde d'azote par le tuyau d'échappement arrière.
Capteur de pression Delta du filtre à particules au diesel (MX-11, MX-13, EPA21)	2200138 ⁽¹⁾	Les défaillances du capteur de pression Delta qui entraînent un suivi inexact du filtre à particules diesel/réduction catalytique sélective peuvent compromettre l'efficacité du système du filtre à particules diesel/réduction catalytique sélective et affecter les émissions d'oxyde d'azote et/ou de particules à la sortie du tuyau d'échappement.
⁽¹⁾ Composantes incluses dans une lettre précédente. ⁽²⁾ Composante additionnelle ajoutée à la couverture de garantie prolongée.		

Si vous avez déjà payé pour remplacer l'une des composantes listées dans le tableau ci-dessus, vous pourriez être admissible à un remboursement des frais de pièces et de main-d'œuvre. Veuillez fournir à votre concessionnaire Kenworth un reçu pour la réparation et votre concessionnaire déposera une réclamation en votre nom. Si elle est approuvée, votre concessionnaire émettra le remboursement.

Afin de localiser votre concessionnaire le plus près, veuillez balayer le code QR dans le coin supérieur droit de la présente ou consulter le localisateur de concessionnaire sur www.Kenworth.com. Au moment de communiquer avec le concessionnaire Kenworth de votre choix, vous référer au code de garantie prolongée (EWC) **9202162** ainsi qu'au NIV listé à la présente.

Si vous êtes le bailleur de ce véhicule, les réglementations fédérales exigent que vous transmettiez une copie de cet avis au locataire et ce, dans un délai de dix jours. Si vous n'êtes plus le propriétaire de ce véhicule, veuillez courrieller les 8 derniers chiffres du NIV ainsi que le nom et l'adresse du nouveau propriétaire à servicebulletins@paccar.com.

Merci,

Service à la clientèle de Kenworth



Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

XX/XX/2026

Subject: CE031: MX Component Specific Emissions Warranty for EMY2022

PACCAR MX-11 and MX-13 Engines

Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Kenworth Customer,

This notice is sent to you in accordance with the requirements of the Canadian Environmental Protection Act, 1999.

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless you experience a problem with your vehicle.

This letter has been sent to inform you that Kenworth Truck Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. **No action is needed on your part.**

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty Coverage (EWC Code 9202162)

Part Name	Part Number	Result of Failure
Fuel Injector (MX-13, EPA21)	2314737PEX ⁽¹⁾ 2383579PEX ⁽¹⁾ 2394548PEX ⁽¹⁾ 2403776PEX ⁽¹⁾ 2403201PEX ⁽¹⁾ 2403778PEX ⁽¹⁾ 2423652PEX ⁽¹⁾ 2423654PEX ⁽¹⁾ 2426854PEX ⁽¹⁾ 2426856PEX ⁽¹⁾ 2429855PEX ⁽¹⁾ 2428774PEX ⁽¹⁾ 2452062PEX ⁽¹⁾ 2460410PEX ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.



A **PACCAR** COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

	2460412PEX ⁽¹⁾ 2460414PEX ⁽¹⁾	
Fuel Injector (MX-11, EPA21)	2314736PEX ⁽¹⁾ 2383578PEX ⁽¹⁾ 2394547PEX ⁽¹⁾ 2403775PEX ⁽¹⁾ 2403200PEX ⁽¹⁾ 2403777PEX ⁽¹⁾ 2423651PEX ⁽¹⁾ 2423653PEX ⁽¹⁾ 2426853PEX ⁽¹⁾ 2426855PEX ⁽¹⁾ 2429854PEX ⁽¹⁾ 2428773PEX ⁽¹⁾ 2452061PEX ⁽¹⁾ 2460409PEX ⁽¹⁾ 2460411PEX ⁽¹⁾ 2460413PEX ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
DPF Delta Pressure Sensor (MX-13, EPA21)	2200138PEX ⁽¹⁾	Failures of the Delta Pressure Sensor may result in inaccurate monitoring of the DPF/SCR could have the potential to compromise the DPF/SCR system effectiveness and affect tailpipe emissions of NOx and/or particulate matter.
Fuel Injection Pump (MX-13, EPA21)	2185361PE ⁽¹⁾ 2344776PEX ⁽²⁾	Failures of the Fuel Injection Pumps that result in inaccurate monitoring of exhaust gases have the potential to compromise SCR system effectiveness and affect tailpipe emissions of NOx.
DPF Delta Pressure Sensor (MX-11, MX-13, EPA21)	2200138 ⁽¹⁾	Failures of the Delta Pressure Sensor that result in inaccurate monitoring of the DPF/SCR have the potential to compromise the DPF/SCR system effectiveness and affect tailpipe emissions of NOx and/or particulate matter.
⁽¹⁾ Components that were included in a previous letter. ⁽²⁾ Additional component added to Extended Warranty Coverage.		

If you have previously paid to replace one of the components listed in the tables above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Kenworth



Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

Dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest dealer please scan the QR code at the top of this letter or use the Dealer Locator at www.Kenworth.com. When contacting your selected Kenworth dealer, refer to Extended Warranty Code (EWC) **9202162** and the VIN listed on this letter.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.

Sincerely,

Kenworth Customer Service



Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

[Fecha]



Asunto: CE031: Garantía de emisiones específicas de componentes de MX para motores EMY2022 PACCAR MX-11 y MX-13

Fecha de vencimiento: Ninguna

Este aviso se aplica a su vehículo. Puede encontrar sus VIN en el frente o dorso de esta página.

Estimado cliente de Kenworth:

Esto no se trata de una retirada ni de una campaña. No es necesario que programe una cita con su distribuidor a menos que su vehículo tenga un problema.

Le enviamos esta carta para informarle que Kenworth Truck Company ha extendido la cobertura de la garantía a ciertos componentes de emisiones instalados en sus vehículos. Sus vehículos contienen una o más de las piezas indicadas en esta carta. **No es necesario que haga nada.**

La cobertura de la garantía de emisiones para los componentes indicados en la tabla que se muestra a continuación se ha extendido a 10 años, 435,000 millas (700,000 km) del vehículo o 22,000 horas de funcionamiento a partir de la fecha de registro de la garantía original, lo que suceda primero.

Tabla 1: Piezas cubiertas por la garantía extendida (Código de garantía extendida 9202162)

Nombre de la pieza	Número de pieza	Resultado de la falla
Inyector de combustible (MX-13, EPA21)	2314737PEX ⁽¹⁾ 2383579PEX ⁽¹⁾ 2394548PEX ⁽¹⁾ 2403776PEX ⁽¹⁾ 2403201PEX ⁽¹⁾ 2403778PEX ⁽¹⁾ 2423652PEX ⁽¹⁾ 2423654PEX ⁽¹⁾ 2426854PEX ⁽¹⁾ 2426856PEX ⁽¹⁾ 2429855PEX ⁽¹⁾ 2428774PEX ⁽¹⁾ 2452062PEX ⁽¹⁾	Un funcionamiento ineficaz del inyector de combustible puede provocar una regeneración insuficiente y una elevada carga de hollín del DPF debido a una combustión irregular del combustible.



A PACCAR COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

	2460410PEX ⁽¹⁾ 2460412PEX ⁽¹⁾ 2460414PEX ⁽¹⁾	
Inyector de combustible (MX-11, EPA21)	2314736PEX ⁽¹⁾ 2383578PEX ⁽¹⁾ 2394547PEX ⁽¹⁾ 2403775PEX ⁽¹⁾ 2403200PEX ⁽¹⁾ 2403777PEX ⁽¹⁾ 2423651PEX ⁽¹⁾ 2423653PEX ⁽¹⁾ 2426853PEX ⁽¹⁾ 2426855PEX ⁽¹⁾ 2429854PEX ⁽¹⁾ 2428773PEX ⁽¹⁾ 2452061PEX ⁽¹⁾ 2460409PEX ⁽¹⁾ 2460411PEX ⁽¹⁾ 2460413PEX ⁽¹⁾	Un funcionamiento ineficaz del inyector de combustible puede provocar una regeneración insuficiente y una elevada carga de hollín del DPF debido a una combustión irregular del combustible.
Bomba de inyección de combustible (MX-13, EPA21)	2185361PE ⁽¹⁾ 2344776PEX ⁽²⁾	Las fallas en las bombas de inyección de combustible que tienen como resultado monitoreos imprecisos de emisiones de gases pueden potencialmente comprometer la efectividad del sistema SCR y afectar las emisiones de NOx del escape.
Sensor de presión Delta del DPF (MX-11, MX-13, EPA21)	2200138 ⁽¹⁾	Las fallas del sensor de presión diferencial que provocan que el monitoreo del DPF/SCR sea inexacto pueden comprometer su efectividad y afectar las emisiones de NOx y/o partículas del tubo de escape.
⁽¹⁾ Componentes que se incluyeron en una carta previa. ⁽²⁾ Componente adicional agregado a la cobertura de la garantía extendida.		

Si anteriormente pagó para reemplazar uno de los componentes mencionados en las tablas de arriba, podría calificar para recibir un reembolso por el costo de las piezas y el trabajo. Entregue a su distribuidor de Kenworth un comprobante por la reparación y el distribuidor presentará el reclamo en su nombre. Si se aprueba, su distribuidor le dará el reembolso.



Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

Para encontrar su distribuidor más cercano, escanee el código QR que aparece en la parte superior de esta carta o utilice la función “Dealer Locator” (Buscador de distribuidores) en www.Kenworth.com. Cuando se comuniquen con el distribuidor de Kenworth que haya elegido, mencione el código de garantía extendida (EWC) **9202162** y el VIN que se incluye en esta carta.

Si usted es el arrendador de este vehículo, las regulaciones federales requieren que envíe una copia de este aviso al arrendatario en un plazo de 10 días. Si ya no es el propietario de este vehículo, envíe por correo electrónico los últimos ocho dígitos del VIN y el nombre y la dirección del nuevo propietario a servicebulletins@paccar.com.

Atentamente.

Kenworth Customer Service



Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

XX/XX/2026

Subject: CE031: MX Component Specific Emissions Warranty for EMY2022

PACCAR MX-11 and MX-13 Engines

Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Kenworth Customer,

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless you experience a problem with your vehicle.

This letter has been sent to inform you that Kenworth Truck Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. **No action is needed on your part.**

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty Coverage (EWC Code 9202162)

Part Name	Part Number	Result of Failure
Fuel Injector (MX-13, EPA21)	2314737PEX ⁽¹⁾ 2383579PEX ⁽¹⁾ 2394548PEX ⁽¹⁾ 2403776PEX ⁽¹⁾ 2403201PEX ⁽¹⁾ 2403778PEX ⁽¹⁾ 2423652PEX ⁽¹⁾ 2423654PEX ⁽¹⁾ 2426854PEX ⁽¹⁾ 2426856PEX ⁽¹⁾ 2429855PEX ⁽¹⁾ 2428774PEX ⁽¹⁾ 2452062PEX ⁽¹⁾ 2460410PEX ⁽¹⁾ 2460412PEX ⁽¹⁾ 2460414PEX ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.



A **PACCAR** COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

Fuel Injector (MX-11, EPA21)	2314736PEX ⁽¹⁾ 2383578PEX ⁽¹⁾ 2394547PEX ⁽¹⁾ 2403775PEX ⁽¹⁾ 2403200PEX ⁽¹⁾ 2403777PEX ⁽¹⁾ 2423651PEX ⁽¹⁾ 2423653PEX ⁽¹⁾ 2426853PEX ⁽¹⁾ 2426855PEX ⁽¹⁾ 2429854PEX ⁽¹⁾ 2428773PEX ⁽¹⁾ 2452061PEX ⁽¹⁾ 2460409PEX ⁽¹⁾ 2460411PEX ⁽¹⁾ 2460413PEX ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
Fuel Injection Pump (MX-13, EPA21)	2185361PE ⁽¹⁾ 2344776PEX ⁽²⁾	Failures of the Fuel Injection Pumps that result in inaccurate monitoring of exhaust gases have the potential to compromise SCR system effectiveness and affect tailpipe emissions of NOx.
DPF Delta Pressure Sensor (MX-11, MX-13, EPA21)	2200138 ⁽¹⁾	Failures of the Delta Pressure Sensor that result in inaccurate monitoring of the DPF/SCR have the potential to compromise the DPF/SCR system effectiveness and affect tailpipe emissions of NOx and/or particulate matter.
⁽¹⁾ Components that were included in a previous letter. ⁽²⁾ Additional component added to Extended Warranty Coverage.		

If you have previously paid to replace one of the components listed in the tables above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Kenworth Dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest Kenworth dealer, please scan the QR code at the top of this letter or use the Dealer Locator at www.Kenworth.com. When contacting your selected Kenworth dealer, refer to Extended Warranty Code (EWC) **9202162** and the VIN(s) listed on this letter.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the



A **PACCAR** COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

VIN and the new owner's name and address to servicebulletins@paccar.com.

Sincerely,

Kenworth Customer Service

Date à être déterminée

Objet : CE031 Garantie relative aux émissions spécifiques des composantes MX pour moteurs
MX-11 et MX-13 EMY2022 de PACCAR

Date d'expiration : Aucune



Cher client Peterbilt,

Nous vous faisons parvenir cet avis conformément aux exigences de la Loi canadienne relative à la protection de l'environnement (1999).

Il ne s'agit pas d'un rappel ni d'une campagne. Vous n'avez pas à prendre rendez-vous avec votre concessionnaire à moins que votre véhicule ne présente un problème.

La présente a pour but de vous informer que Peterbilt Motors Company a prolongé la couverture de garantie de certaines composantes relatives aux émissions installées sur votre(vos) véhicule(s). Votre (vos) véhicule(s) est (sont) équipé(s) d'une ou de plusieurs des pièces listées à la présente. **Aucune action n'est requise de votre part.**

La couverture de garantie relative aux émissions pour les composantes listées dans le tableau ci-après a été prolongée à 10 ans/700 000 km, ou 22 000 heures de fonctionnement du moteur à compter de la date d'enregistrement de la garantie originale, selon la première éventualité.

Tableau 1 Pièces couvertes par la garantie prolongée (EWC Code 9480836)

Nom de la pièce	No. de la pièce	Résultat de la défectuosité
Injecteur de carburant (MX-13, EPA21)	2314737PEX ⁽¹⁾ 2383579PEX ⁽¹⁾ 2394548PEX ⁽¹⁾ 2403776PEX ⁽¹⁾ 2403201PEX ⁽¹⁾ 2403778PEX ⁽¹⁾ 2423652PEX ⁽¹⁾ 2423654PEX ⁽¹⁾ 2426854PEX ⁽¹⁾ 2426856PEX ⁽¹⁾ 2429855PEX ⁽¹⁾ 2428774PEX ⁽¹⁾ 2452062PEX ⁽¹⁾ 2460410PEX ⁽¹⁾ 2460412PEX ⁽¹⁾ 2460414PEX ⁽¹⁾	Une performance insuffisante de l'injecteur de carburant peut générer une régénération insuffisante ainsi qu'une accumulation importante de suie sur le filtre à particules diesel par suite d'une combustion inégale du carburant.

Injecteur de carburant (MX-11, EPA21)	2314736PEX ⁽¹⁾ 2383578PEX ⁽¹⁾ 2394547PEX ⁽¹⁾ 2403775PEX ⁽¹⁾ 2403200PEX ⁽¹⁾ 2403777PEX ⁽¹⁾ 2423651PEX ⁽¹⁾ 2423653PEX ⁽¹⁾ 2426853PEX ⁽¹⁾ 2426855PEX ⁽¹⁾ 2429854PEX ⁽¹⁾ 2428773PEX ⁽¹⁾ 2452061PEX ⁽¹⁾ 2460409PEX ⁽¹⁾ 2460411PEX ⁽¹⁾ 2460413PEX ⁽¹⁾	Une performance insuffisante de l'injecteur de carburant peut générer une régénération insuffisante ainsi qu'une accumulation importante de suie sur le filtre à particules diesel par suite d'une combustion inégale du carburant.
Pompe d'injection de carburant (MX-13, EPA21)	2185361PEX ⁽¹⁾ 2344776PEX ⁽²⁾	Les défaillances des pompes d'injection de carburant qui entraînent une surveillance inexacte des gaz d'échappement peuvent compromettre l'efficacité du système SCR et affecter les émissions d'oxyde d'azote par le tuyau d'échappement arrière.
Capteur de pression du filtre à particules diesel Delta (MX-11, MX-13, EPA21)	2200138 ⁽¹⁾	Les défaillances du capteur de pression Delta qui entraînent un suivi inexact du filtre à particules diesel/réduction catalytique sélective peuvent compromettre l'efficacité du système du filtre à particules diesel/réduction catalytique sélective et affecter les émissions d'oxyde d'azote et/ou de particules à la sortie du tuyau d'échappement.
⁽¹⁾ Composantes qui étaient incluses dans une lettre précédente. ⁽²⁾ Composante additionnelle ajoutée à la couverture de garantie prolongée.		

Si vous avez déjà payé pour remplacer l'une des composantes listées dans le tableau ci-dessus, vous pourriez être admissible à un remboursement des frais de pièces et de main-d'œuvre. Veuillez fournir à votre concessionnaire Peterbilt un reçu pour la réparation et votre concessionnaire déposera une réclamation en votre nom. Si elle est approuvée, votre concessionnaire émettra le remboursement.

Afin de localiser votre concessionnaire Peterbilt le plus près, veuillez balayer le code QR dans le coin supérieur droit de la présente ou consulter Trouver un concessionnaire sur www.Peterbilt.com. Au moment de communiquer avec le concessionnaire de votre choix, vous référer au code de garantie prolongée (EWC) **9480836** ainsi qu'au NIV listé ci-après ou au verso de la présente.

Si vous êtes le bailleur de ce véhicule, les réglementations fédérales exigent que vous transmettiez une copie de cet avis au locataire et ce, dans un délai de dix jours. Si vous n'êtes plus le propriétaire de ce véhicule, veuillez courrieller les 8 derniers chiffres du NIV ainsi que le nom et l'adresse du nouveau propriétaire à servicebulletins@paccar.com.

Merci,

Service à la clientèle de Peterbilt



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

XX/XX/2026

Subject: CE031: MX Component Specific Emissions Warranty for EMY2022
PACCAR MX-11 and MX-13 Engines
Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Peterbilt Customer,

This notice is sent to you in accordance with the requirements of the Canadian Environmental Protection Act, 1999.

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless your vehicle experiences a problem.

This letter has been sent to inform you that Peterbilt Motors Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. **No action is needed on your part.**

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty (EWC Code 9480836)

Part Name	Part Number	Result of Failure
Fuel Injector (MX-13, EPA21)	2314737PEX ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
	2383579PEX ⁽¹⁾	
	2394548PEX ⁽¹⁾	
	2403776PEX ⁽¹⁾	
	2403201PEX ⁽¹⁾	
	2403778PEX ⁽¹⁾	
	2423652PEX ⁽¹⁾	
	2423654PEX ⁽¹⁾	
	2426854PEX ⁽¹⁾	
	2426856PEX ⁽¹⁾	
	2429855PEX ⁽¹⁾	
	2428774PEX ⁽¹⁾	
	2452062PEX ⁽¹⁾	
	2460410PEX ⁽¹⁾	



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

	2460412PEX ⁽¹⁾ 2460414PEX ⁽¹⁾	
Fuel Injector (MX-11, EPA21)	2314736PEX ⁽¹⁾ 2383578PEX ⁽¹⁾ 2394547PEX ⁽¹⁾ 2403775PEX ⁽¹⁾ 2403200PEX ⁽¹⁾ 2403777PEX ⁽¹⁾ 2423651PEX ⁽¹⁾ 2423653PEX ⁽¹⁾ 2426853PEX ⁽¹⁾ 2426855PEX ⁽¹⁾ 2429854PEX ⁽¹⁾ 2428773PEX ⁽¹⁾ 2452061PEX ⁽¹⁾ 2460409PEX ⁽¹⁾ 2460411PEX ⁽¹⁾ 2460413PEX ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
Fuel Injection Pump (MX-13, EPA21)	2185361PE ⁽¹⁾ 2344776PEX ⁽²⁾	Failures of the Fuel Injection Pumps that result in inaccurate monitoring of exhaust gases have the potential to compromise SCR system effectiveness and affect tailpipe emissions of NOx.
DPF Delta Pressure Sensor (MX-11, MX-13, EPA21)	2200138 ⁽¹⁾	Failures of the Delta Pressure Sensor that result in inaccurate monitoring of the DPF/SCR have the potential to compromise the DPF/SCR system effectiveness and affect tailpipe emissions of NOx and/or particulate matter.
⁽¹⁾ Components that were included in a previous letter. ⁽²⁾ Additional component added to Extended Warranty Coverage.		

If you have previously paid to replace any of the components listed in the table above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Peterbilt dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest Peterbilt dealer, please scan the QR code at the top of this letter or use Find a Dealer at www.Peterbilt.com. When contacting your selected Peterbilt dealer, refer to Extended Warranty Code (EWC) **9480836** and the VIN(s) listed on this letter.



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.

Sincerely,

Peterbilt Customer Service



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

[Fecha]

Asunto: CE031: Garantía de emisiones específicas de componentes de MX para motores EMY2022 PACCAR MX-11 y MX-13

Fecha de vencimiento: Ninguna



Estimado cliente de Peterbilt:

Esto no se trata de una retirada ni de una campaña. No es necesario que programe una cita con su distribuidor a menos que su vehículo tenga un problema.

Le enviamos esta carta para informarle que Peterbilt Motors Company ha extendido la cobertura de la garantía a ciertos componentes de emisiones instalados en sus vehículos. Sus vehículos contienen una o más de las piezas indicadas en esta carta. **No es necesario que haga nada.**

La cobertura de la garantía de emisiones para los componentes indicados en la tabla que se muestra a continuación se ha extendido a 10 años, 435,000 millas (700,000 km) del vehículo o 22,000 horas de funcionamiento a partir de la fecha de registro de la garantía original, lo que suceda primero.

Tabla 1: Piezas cubiertas por la garantía extendida (Código de garantía extendida 9480836)

Nombre de la pieza	Número de pieza	Resultado de la falla
Inyector de combustible (MX-13, EPA21)	2314737PEX ⁽¹⁾	Un funcionamiento ineficaz del inyector de combustible puede provocar una regeneración insuficiente y una elevada carga de hollín del DPF debido a una combustión irregular del combustible.
	2383579PEX ⁽¹⁾	
	2394548PEX ⁽¹⁾	
	2403776PEX ⁽¹⁾	
	2403201PEX ⁽¹⁾	
	2403778PEX ⁽¹⁾	
	2423652PEX ⁽¹⁾	
	2423654PEX ⁽¹⁾	
	2426854PEX ⁽¹⁾	
	2426856PEX ⁽¹⁾	
	2429855PEX ⁽¹⁾	
	2428774PEX ⁽¹⁾	
	2452062PEX ⁽¹⁾	
	2460410PEX ⁽¹⁾	
	2460412PEX ⁽¹⁾	
	2460414PEX ⁽¹⁾	



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

Inyector de combustible (MX-11, EPA21)	2314736PEX ⁽¹⁾ 2383578PEX ⁽¹⁾ 2394547PEX ⁽¹⁾ 2403775PEX ⁽¹⁾ 2403200PEX ⁽¹⁾ 2403777PEX ⁽¹⁾ 2423651PEX ⁽¹⁾ 2423653PEX ⁽¹⁾ 2426853PEX ⁽¹⁾ 2426855PEX ⁽¹⁾ 2429854PEX ⁽¹⁾ 2428773PEX ⁽¹⁾ 2452061PEX ⁽¹⁾ 2460409PEX ⁽¹⁾ 2460411PEX ⁽¹⁾ 2460413PEX ⁽¹⁾	Un funcionamiento ineficaz del inyector de combustible puede provocar una regeneración insuficiente y una elevada carga de hollín del DPF debido a una combustión irregular del combustible.
Bomba de inyección de combustible (MX-13, EPA21)	2185361PE ⁽¹⁾ 2344776PEX ⁽²⁾	Las fallas en las bombas de inyección de combustible que tienen como resultado monitoreos imprecisos de emisiones de gases pueden potencialmente comprometer la efectividad del sistema SCR y afectar las emisiones de NOx del escape.
Sensor de presión Delta del DPF (MX-11, MX-13, EPA21)	2200138 ⁽¹⁾	Las fallas del sensor de presión diferencial que provocan que el monitoreo del DPF/SCR sea inexacto pueden comprometer su efectividad y afectar las emisiones de NOx y/o partículas del tubo de escape.
⁽¹⁾ Componentes que se incluyeron en una carta previa. ⁽²⁾ Componente adicional agregado a la cobertura de la garantía extendida.		

Si anteriormente pagó para reemplazar cualquiera de los componentes mencionados en la tabla de arriba, podría calificar para recibir un reembolso por el costo de las piezas y el trabajo. Entregue a su distribuidor de Peterbilt un comprobante de la reparación y este presentará un reclamo en su nombre. Si se aprueba, su distribuidor le dará el reembolso.

Para encontrar el distribuidor de Peterbilt más cercano, escanee el código QR que aparece en la parte superior de esta carta o utilice la función “Find a Dealer” (Buscar un distribuidor) en www.Peterbilt.com. Cuando se comunique con el distribuidor que haya elegido, mencione el



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

código de garantía extendida (EWC) **9480836** y el VIN que se incluye abajo o al reverso de esta carta.

Si usted es el arrendador de este vehículo, las regulaciones federales requieren que envíe una copia de este aviso al arrendatario dentro de los diez días. Si ya no es el propietario de este vehículo, envíe por correo electrónico los últimos 8 dígitos del VIN y el nombre y la dirección del nuevo propietario a servicebulletins@paccar.com.

Atentamente.

Peterbilt Customer Service



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

XX/XX/2026

Subject: CE031: MX Component Specific Emissions Warranty for EMY2022
PACCAR MX-11 and MX-13 Engines
Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Peterbilt Customer,

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless your vehicle experiences a problem.

This letter has been sent to inform you that Peterbilt Motors Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. **No action is needed on your part.**

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty (EWC Code 9480836)

Part Name	Part Number	Result of Failure
Fuel Injector (MX-13, EPA21)	2314737PEX ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
	2383579PEX ⁽¹⁾	
	2394548PEX ⁽¹⁾	
	2403776PEX ⁽¹⁾	
	2403201PEX ⁽¹⁾	
	2403778PEX ⁽¹⁾	
	2423652PEX ⁽¹⁾	
	2423654PEX ⁽¹⁾	
	2426854PEX ⁽¹⁾	
	2426856PEX ⁽¹⁾	
	2429855PEX ⁽¹⁾	
	2428774PEX ⁽¹⁾	
	2452062PEX ⁽¹⁾	
	2460410PEX ⁽¹⁾	
	2460412PEX ⁽¹⁾	
	2460414PEX ⁽¹⁾	



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

Fuel Injector (MX-11, EPA21)	2314736PEX ⁽¹⁾ 2383578PEX ⁽¹⁾ 2394547PEX ⁽¹⁾ 2403775PEX ⁽¹⁾ 2403200PEX ⁽¹⁾ 2403777PEX ⁽¹⁾ 2423651PEX ⁽¹⁾ 2423653PEX ⁽¹⁾ 2426853PEX ⁽¹⁾ 2426855PEX ⁽¹⁾ 2429854PEX ⁽¹⁾ 2428773PEX ⁽¹⁾ 2452061PEX ⁽¹⁾ 2460409PEX ⁽¹⁾ 2460411PEX ⁽¹⁾ 2460413PEX ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
Fuel Injection Pump (MX-13, EPA21)	2185361PE ⁽¹⁾ 2344776PEX ⁽²⁾	Failures of the Fuel Injection Pumps that result in inaccurate monitoring of exhaust gases have the potential to compromise SCR system effectiveness and affect tailpipe emissions of NOx.
DPF Delta Pressure Sensor (MX-11, MX-13, EPA21)	2200138 ⁽¹⁾	Failures of the Delta Pressure Sensor that result in inaccurate monitoring of the DPF/SCR have the potential to compromise the DPF/SCR system effectiveness and affect tailpipe emissions of NOx and/or particulate matter.
⁽¹⁾ Components that were included in a previous letter. ⁽²⁾ Additional component added to Extended Warranty Coverage.		

If you have previously paid to replace any of the components listed in the table above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Peterbilt dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest Peterbilt dealer, please scan the QR code at the top of this letter or use Find a Dealer at www.Peterbilt.com. When contacting your selected Peterbilt dealer, refer to Extended Warranty Code (EWC) **9480836** and the VIN(s) listed on this letter.



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.

Sincerely,

Peterbilt Customer Service