

**Technical Service Bulletin (TSB)**  
**Outer Belt Molding Has Excessive Gap**

<b>REFERENCE:</b>	<b>TSB:</b> 23-004-26 <b>GROUP:</b> 23 - Body	<b>Date:</b>	February 17, 2026	<b>REVISION:</b>	—
<b>VEHICLES AFFECTED:</b>	<b>2024 - 2025 (DD) RAM 3500 Cab Chassis</b> <b>2024 - 2025 (DP) RAM 4500/5500 Cab Chassis</b> <b>2024 - 2025 (DJ) RAM 2500 Pickup</b> <b>2024 - 2025 (D2) RAM 3500 Pickup</b> This bulletin applies to vehicles built on or after June 29, 2025 (MDH 0629XX) and on or before July 02, 2025 (MDH 0702XX) that are equipped without Chrome Belt Moldings (Sales Code MME).			<b>MARKET APPLICABILITY:</b> <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> EE <input type="checkbox"/> IAP <input type="checkbox"/> SA <input type="checkbox"/> CH <b>NOTE:</b> This bulletin applies to North America markets.	
<b>CUSTOMER SYMPTOM:</b>	<b>Customers may comment on the following:</b> <ul style="list-style-type: none"> <li>The outer belt molding appears warped or deformed causing a gap between the edge of the door and the molding.</li> </ul> <p align="center"><b>NOTE: This condition can appear on any of the doors.</b></p>				
<b>CAUSE:</b>	Belt molding deformation				

**REPAIR SUMMARY:**

This bulletin involves replacing one or more door outer belt moldings.

**CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-51-16-9Q	Molding, Outer Door - Replace One Front Door 0 - Introduction	6 - Electrical and Body Systems	0.4 Hrs.
23-51-16-9R	Molding, Outer Belt - Replace Both Front Doors 0 - Introduction	6 - Electrical and Body Systems	0.8 Hrs.
23-51-16-9S	Molding, Outer Door - Replace One Rear Door 0 - Introduction	6 - Electrical and Body Systems	0.2 Hrs.
23-51-16-9T	Molding, Outer Door - Replace Both Rear Doors 0 - Introduction	6 - Electrical and Body Systems	0.3 Hrs.
Failure Code	ZZ	Service Action	

## SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	55112376AJ	Weatherstrip, Front Door Belt Outer	Front Door - Short Right
1 (AR)	55112377AJ	Weatherstrip, Front Door Belt Outer	Front Door - Short Left
1 (AR)	55369292AG	Weatherstrip, Front Door Belt Outer	Front Door - Long Right
1 (AR)	55369293AG	Weatherstrip, Front Door Belt Outer	Front Door - Long Left
1 (AR)	55372138AJ	Weatherstrip, Rear Door Belt Outer	Rear Door - Right
1 (AR)	55372139AJ	Weatherstrip, Rear Door Belt Outer	Rear Door - Left

## DIAGNOSIS:

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

## REPAIR PROCEDURE:

1. Remove the outside rearview mirror for the affected door(s) (if required). Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 23 - Body / Exterior / Mirror, Outside Rearview / Removal.
2. Replace the affected door outer belt molding. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 23 - Body / Doors - Front / Molding, Door Belt, Outer / Removal and Installation.
3. Install the outside rearview mirror for the affected door(s) (if required). Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 23 - Body / Exterior / Mirror, Outside Rearview / Installation.

## POLICY:

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*