

SUBJECT: LICENSE PLATE BRACKET REPLACEMENT**VEHICLE(S) AFFECTED:** 2024 CFMOTO Papio CL and Papio SS Motorcycles**ISSUED:** October 24, 2023

PLEASE NOTE: This dealer only warranty bulletin is intended to inform service personnel regarding factory authorized warranty repairs to CFMOTO products. No other warranty coverage applies, is implied, or is to be inferred as a result of this publication. Questions regarding this publication should be directed to CFMOTO Technical Service.

Dealer Sign-off Section – Please notify the appropriate personnel	
Sales Manager	
Warranty/Svc Manager	
Technician(s)	

ISSUE:

Rear turn signals may rattle against the license plate bracket while the vehicle goes over bumps.

SOLUTION:

CFMOTO-USA is issuing **Warranty Bulletin WAR-2023-06** to replace the license plate bracket with a redesigned bracket. This bulletin should be performed:

- 1) On affected 2024 Papio CL or SS motorcycles during uncrating and assembly.
- 2) On affected 2024 Papio CL or SS motorcycles after scheduling the repair with the owners. Brackets must be installed by your dealership.

AFFECTED VEHICLE IDENTIFICATION NUMBERS:

- **Papio CL:** Last 4 digits of the VIN must be 0404 or below.
- **Papio SS:** Last 4 digits of the VIN must be 0402 or below.

NOTE: Parts for this bulletin *DO NOT* automatically ship.

Your dealership must order parts as described on page 3.