



## STAR ONLINE PUBLICATION



**Case Number:** S2605000002

**Release Date:** March 2026

**Symptom/Vehicle Issue:** Whoosh Or Click Noise Heard From Brake Assembly eBooster When Pressing Brake Pedal And After A Recent Repair.

**Models Affected:** 2025-2026 Ram 1500 (DT)

**Discussion:** A potential cause of noise in the brake assembly after a recent repair could be from air being present in the eBooster. Service Library bleed procedures have been updated to include pressure bleeding should be done with the tool pressurized to 40-50 PSI. Be sure to use the updated pressure bleed information. Refer to Service Library 05 - Brakes / Standard Procedure, Pressure Bleeding for more information.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**