


| | | |
|---|----------------------------------|---|
|  HYUNDAI Technical Service Bulletin | GROUP BODY | NUMBER 26-BD-001H |
| | DATE MARCH 2026 | MODEL(S) SANTA FE (MX5A), SANTA FE HYBRID (MX5A HEV) |
| SUBJECT: 2ND ROW CAPTAIN'S CHAIRS ARMREST CAP DETACHMENT | | |

*** IMPORTANT**

This field action requires justification in the form of a customer concern, and a confirmed case for the related symptom outlined in the TSB, prior to any repair work. If justification requirements are not met, any submitted claims are subject to debit. 5 / 60,000 New Vehicle Limited Warranty applies. See Warranty Information section for more details.

Description: Some Santa Fe (MX5A) and Santa Fe Hybrid (MX5A HEV) vehicles equipped with 2nd row captain's chairs have an armrest cap that may detach. This bulletin provides the procedure to replace the armrest cap on the 2nd row captain's chairs with a revised part.



Applicable Vehicles:

| Model Year | Model | Production Dates |
|------------|----------------------------|-------------------------|
| 2025 | Santa Fe (MX5A) | 02/04/2025 - 05/27/2025 |
| | Santa Fe Hybrid (MX5A HEV) | 03/16/2025 - 05/06/2025 |

Parts Information:

| Model | Part Name | Part Number | | QTY | Interior Color |
|--|-----------|----------------|------------------|-----|----------------|
| | | Current | New | | |
| Santa Fe (MX5A), Santa Fe Hybrid (MX5A HEV) | Cap | 89393-R6310NNB | 89393-R6310NNBQH | 2 | Black |
| | | 89393-R6310PCR | 89393-R6310PCRQH | 2 | Brown |
| | | 89393R6310YSY | 89393-R6310YSYQH | 2 | Gray |
| | | 89393R6310MCG | 89393-R6310MCGQH | 2 | Beige |

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

Warranty Information:

| Model | Op. Code | Operation | Op. Time | Causal Part | Nature Code | Cause Code |
|--|----------|--|----------|----------------|-------------|------------|
| Santa Fe (MX5A), Santa Fe Hybrid (MX5A HEV) | 50DA42R0 | 2 nd Row Captain's Chairs Armrest Cap Replacement | 0.3 M/H | 89393-R6310NNB | A36 | ZZ1 |

NOTE 1: Submit claim on Claim Entry Screen as "Campaign" type.

NOTE 2: 5 / 60,000 New Vehicle Limited Warranty (NVLW) applies to the part(s) and repair procedure(s) outlined in this TSB. Prior to beginning any repair work, ensure the part(s) associated with the repair procedure are within NVLW, observing mileage and Warranty Start Date or date of first use. If the subject part(s) are out of warranty coverage, the dealer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

NOTE 3: If any part(s) not subject to this TSB are found in need of replacement while performing the repair procedure, and the affected part(s) are still under warranty, the dealer may submit a separate claim using the same repair order. If the part(s) not subject to this TSB are out of warranty coverage, the dealer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

NOTE 4: This TSB includes repair justification photos. Op times include VIN, Mileage, and repair justification photos as outlined in the Digital Documentation Policy.

NOTE 5: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. Claim is subject to debit if the part is not returned.

Service Procedure:**DIGITAL DOCUMENTATION**

This TSB includes repair justification photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

1. Remove the 2nd row captain's chair armrest cap with a plastic trim removal tool.



2. Install the new cap by pushing it until it is fully seated and flush with the side of the armrest.



3. Repeat steps 1-2 on the opposite side seat.

- 4.

DIGITAL
DOCUMENTATION



Using the STUI camera function, take a photo of the original armrest caps.

Upload the photos to STUI.

NOTE: If the STUI camera function is **NOT** used, write the last 6 digits of the VIN and the date of repair on a piece of paper to include in the photo.



5. The service procedure is now complete.