



Service Bulletin

Bulletin No.: PIT6497

Date: March, 2026

PRELIMINARY INFORMATION

Subject: Key Missing Or Check For Key Message On DIC While Driving

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade	2024-2025		ALL	ALL	ALL	ALL
Cadillac	Escalade ESV	2024-2025		ALL	ALL	ALL	ALL
Chevrolet	Tahoe	2024-2025		ALL	ALL	ALL	ALL
GMC	Yukon	2024-2025		ALL	ALL	ALL	ALL
GMC	Yukon XL	2024-2025		ALL	ALL	ALL	ALL

Involved Region or Country	North America
Additional Options (RPO)	BTM
Condition	Some customers may experience a Key Missing Or Check For Key Message On DIC While Driving
Cause	Software Anomaly

Correction

Update the K9 Body Control Module (BCM) using the latest software in TLC/SPS.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Labor Time

Version	1
Modified	03/17/2026- Created On

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2026 General Motors. All Rights Reserved.