



# Service Bulletin

Bulletin No.: PIT6496

Date: March, 2026

## PRELIMINARY INFORMATION

**Subject: Service Headlight Message With DTC's B1B5F sym49 or B1B60 sym49 set in History**

| Brand:   | Model:       | Model Year: |    | VIN:                |         | Engine: | Transmission: |
|----------|--------------|-------------|----|---------------------|---------|---------|---------------|
|          |              | from        | to | from                | to      |         |               |
| Cadillac | Escalade     | 2026        |    | November 12th, 2025 | Current | All     | All           |
| Cadillac | Escalade ESV | 2026        |    | November 12th, 2025 | Current | All     | All           |

|                                   |   |
|-----------------------------------|---|
| <b>Involved Region or Country</b> | North America, MEO, Korea, Japan                            |
| <b>Condition</b>                  | Some customers may comment of a "Service Headlamp" message. |
| <b>Cause</b>                      | GM Engineering is investigating.                            |

### Correction

Perform the following diagnostic steps:

If the DTCs are current:

- a. Follow SI diagnostics as required.

If the DTC's are history:

- a. Clear history DTCs.
- b. Verify that the headlights and auto level function of the headlamp is functioning when the vehicle is started. Do this by covering the ambient light sensor on the dash and visually confirming the vertical (up/down) movement of the headlamp beam pattern and/or interior lenses.
- c. Verify that the "service headlamp" message does not appear and no DTCs are set.
- d. If the headlights are operating properly with no messages or DTCs then return the vehicle to the customer, if not then follow normal SI diagnostics as necessary.

GM Engineering is investigating the source of this message/DTCs and in the meantime please continue to drive your vehicle. This PI will be updated or replaced with TSB once a determination has been made.

GM Engineering is investigating the source of this message/DTCs and in the meantime please continue to drive your vehicle. This PI will be updated or replaced with TSB once a determination has been made.

**Warranty Information**

GM Engineering is investigating the source of this message/DTCs and in the meantime please continue to drive your vehicle. This PI will be updated or replaced with TSB once a determination has been made.

| Labor Operation  | Description                                       | Labor Time |
|--|---|------------|
| 2081488*   | Clear DTC's and verify proper headlight operation | 0.3 Hrs.   |
| *This is a unique Labor Operation for Bulletin use only. |   |            |

|          |                      |
|----------|----------------------|
| Version  | 1                    |
| Modified | 3/17/2026 Created on |

